

WATER TANK CLEANING & DISINFECTION

COMPLETION REPORT

FOR

MULTIPLIX

Client : **Multiplex Services LLC.**
Contact Person: Mr. Vishnudeth Pamideth
Asst. Facilities Manager
Site Details : Sheikh Zayed Desert Learning
Center, Al Ain, U. A. E.
Date : 26 May 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.
TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16009

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISANU		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTRE			CONTACT NO: 0564172552		
TANK DETAILS: R.B.C. BYPASS STEEL TANK. 2J			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18-05-2019		18-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Biof plus Quantity 300ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
OXYGEN LEVEL - 20.9					
ABOVE MENTIONED TANK CLEANED AND DISINFECTED					
Crystalline Representative: HARIS			Signature: [Signature]		

Faisal Olyf
10-90566


Date of Cleaning: 18-05-2019

PHOTOGRAPHS
BASEMENT LEVEL SEWAGE WATER STEEL TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16010

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTRE			CONTACT NO: 056 4142552		
TANK DETAILS: POST-RBC W. TREATMENT TANK			LOCATION DETAILS: - 10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input checked="" type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18-05-2019		18-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARECO Biof pills Quantity 300 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
OXYGEN LEVEL. 20.9					
ABOVE MENTIONED W. TANK. CLEANED & DISINFECTED					
Crystalline Representative: HARIS			Signature: [Signature]		

Faisal Q. Al...
10# 90566



CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 18-05-2019

PHOTOGRAPHS
BASEMENT LEVEL PRE WATER TREATMENT GRP TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16011

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DESERTI LEARNING CENTRE			CONTACT NO: 0564142552		
TANK DETAILS: PRE-RBC. W. TREATMENT TANK			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input checked="" type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/05/2019		18-10/5/2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO L. plus Quantity 300ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
OXYGEN LEVEL 20.9					
ABOVE MENTIONED W. TANK CLEANED & DISINFECTED					
Crystalline Representative: HARIS			Signature: [Signature]		

Faisal Qasbi
10#90566

Date of Cleaning: 18-05-2019

PHOTOGRAPHS
BASEMENT LEVEL POST WATER TREATMENT GRP TANK

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16017

CUSTOMER: MULYI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DISERI LEARNING CENTRE-			CONTACT NO: 056442552		
TANK DETAILS: RO REJECT STEEL TANK			LOCATION DETAILS: - 10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input checked="" type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		20-05-2019		20-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO & PLUS Quantity 300 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: OXYGEN LEVEL 20.9					
ABOVE MENTIONED W. TANK CLEANED & DISINFECTED					
Crystalline Representative: HARI			Signature: HARI		

Faisal Q...




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20-05-2019

PHOTOGRAPHS
RO REJECT STEEL TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16016

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTRE			CONTACT NO: 0564172552		
TANK DETAILS: SOLAR MAKE-UP STEEL TANK			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input checked="" type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19-05-2019		19-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARECO BIO & plus Quantity 200ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
OXYGEN LEVEL - 20.4					
ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED					
Crystalline Representative:			Signature:		

Faisal



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 19-05-2019

PHOTOGRAPHS
SOLAR MAKE-UP STEEL WATER TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16015

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DISERTY LEARNING CENTRE			CONTACT NO: 0564172552		
TANK DETAILS: CIP TANK			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19-05-2019		19-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIOE. PLUS Quantity 100ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
OXYGEN LEVEL 20.9					
ABOVE MENTIONED W. TANK CLEANED & DISINFECTED					
Crystalline Representative: HARIS			Signature: [Signature]		

Faisal [Signature]




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 19-05-2019

PHOTOGRAPHS
CIP SINTEX WATER TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16013

CUSTOMER: MULIPILEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTRE			CONTACT NO: 0564142552		
TANK DETAILS: TSE PRE STORAGE TANK			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS		DRAIN LINE	VALVES
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19 -05-2019		19 -05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & plus Quantity 400ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: OXYGEN LEVEL 20.9					
ABOVE MENTIONED W. TANK CLEANED & DISINFECTED					
Crystalline Representative: HARIS			Signature: [Signature]		

Faisal Oly.



Date of Cleaning: 19-05-2019

PHOTOGRAPHS
TSE PRE STORAGE GRP TANK

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16012

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DISERT LEARNING CENTRE			CONTACT NO: 0564172552		
TANK DETAILS: TREATED W. TANK. 1+1			LOCATION DETAILS: -10		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	LEAKS		DRAIN LINE	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		20-05-2019		20-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIOG plus Quantity 500ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: OXYGEN LEVEL-20.9					
ABOVE MENTIONED W. TANK CLEANED & DISINFECTED					
Crystalline Representative: HABIS			Signature: [Signature]		

Faisal [Signature]

Date of Cleaning: 20-05-2019

PHOTOGRAPHS
TREATED GRP WATER TANK (01 & 02)

BEFORE


GRP WATER TANK- 01



GRP WATER TANK- 02



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

16019

CUSTOMER: MULTI PLEX			CONTACT PERSON: MR. VISHNU		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTRE			CONTACT NO: 0564142552		
TANK DETAILS: BLOW-DOWN-TANK. COOLING TOWER			LOCATION DETAILS: CT-YARI		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input checked="" type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	<input type="checkbox"/> LEAKS	<input type="checkbox"/> DRAIN LINE	<input type="checkbox"/> VALVES	<input type="checkbox"/> FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		20-05-2019		20-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & plus Quantity 300MC					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: OXYGEN LEVEL .209					
ABOVE MENTIONED WATER TANK (CLEANED) & (DISINFECTED)					
Crystalline Representative: HARIS			Signature: HARIS		

CLEANER WATER GREENER TOMORROW

M. Rizwan

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel : +971 55 7167017



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 20-05-2019

PHOTOGRAPHS
BLOW DOWN TANK- COOLING TOWER

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17060

CUSTOMER: <u>MULTIFLEX FM</u>			CONTACT PERSON: <u>ARSHAD ALI ANSARI</u>		
SITE DETAILS: <u>SHEIKH ZAYED DESERT LEARNING CENTER ALAIN</u>			CONTACT NO: <u>056-5015247</u>		
TANK DETAILS: <u>CONDENSATE WATER TANK</u>			LOCATION DETAILS: <u>LOADING BAY AREA</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LADDER IN		LADDER OUT		LEAKS	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>21-05-2019</u>		<u>21-05-2020</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO CARE 8 BIO PLUS</u> Quantity <u>150 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>TANK CLEANED 8 DISINFECTED</u>					
Crystalline Representative: <u>KANSARI</u>			Signature: _____		

Arshad Ali, BOMX-3975



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 21-05-2019

PHOTOGRAPHS
CONDENSATE WATER TANK – LOADING BAY AREA

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17062

CUSTOMER: <u>MULTIFLEX FMI</u>			CONTACT PERSON: <u>ARSHAD ALI ANSARI</u>		
SITE DETAILS: <u>SHEIKH ZAYED DESERT LEARNING CENTER DL AIN</u>			CONTACT NO: <u>056-5015247</u>		
TANK DETAILS: <u>STORM WATER TANK</u>			LOCATION DETAILS: <u>LOADING BAY AREA</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<u>130</u> M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>21-05-2019</u>		<u>21-05-2020</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO CARE 8 BIOPLUS</u> Quantity <u>150 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>TANK CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>IC ANSARI</u>			Signature: _____		

Arshad Ali Ansari
Box-3785
[Signature]

Date of Cleaning: 21-05-2019

PHOTOGRAPHS
STORM WATER TANK- LOADING BAY AREA

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17064

CUSTOMER: MULTIFLEX FM			CONTACT PERSON: MR. ARSHAD ALI ANSARI		
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTER AL AIN			CONTACT NO: 056-5015249		
TANK DETAILS: SEWAGE TANK			LOCATION DETAILS: LOADING BAY AREA		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> COVERED					
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		23-05-2019		23-05-2020	
CHEMICALS & EQUIPMENTS USED					
1. CARELO CARE & BIO PLUS Quantity 150 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
TANK CLEANED & DISINFECTED. OXYgen - 20.9% CO - 0 PPM LEL - 2% H ₂ S - 1 PPM					
Crystalline Representative: ANSARI			Signature: _____		

Arshad Ali Box - 3775

Date of Cleaning: 23-05-2019

PHOTOGRAPHS
SEWAGE TANK- LOADING BAY AREA

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

1565

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: MULTIFLEX FM	CONTACT PERSON: MR. ARSHAD ALI ANSARI
SITE DETAILS: SHEIKH ZAYED DESERT LEARNING CENTER	CONTACT NUMBER: 056-5515249
NAME OF MANHOLE: GREASE TRAP	LOCALISATION: PUMP ROOM
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS:

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	23-05-2019	23-05-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: GREASE CLEANED & DISINFECTED

Crystalline representative: IC ANSARI	Signature:
Customer/Customer representative:	Signature:

CLEANER WATER GREENER TOMORROW

Arshad Ali
Bomx-3725

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 23-05-2019

PHOTOGRAPHS
GREASE TRAP- PUMP ROOM

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17063

CUSTOMER: <u>MULTIFLEX FM</u>			CONTACT PERSON: <u>ARSHAD ALI ANSARI</u>		
SITE DETAILS: <u>SHEIKH ZAYED DESERT LEARNING CENTER DUBAI</u>			CONTACT NO: <u>056-5015247</u>		
TANK DETAILS: <u>STEEL TANK</u>			LOCATION DETAILS: <u>LEVEL (-10) FIRE PUMP ROOM</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	
<input type="checkbox"/> LADDER IN		<input type="checkbox"/> LADDER OUT		<input type="checkbox"/> DAMAGED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>21-05-2019</u>		<u>21-05-2020</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO CARE 8 BIO PLUS</u> Quantity <u>150 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>TANK CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>K ANSARI</u>			Signature: <u>[Signature]</u>		

Arshad Ali
056-3775
[Signature]





CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 21-05-2019

PHOTOGRAPHS
STEEL WATER TANK- FIRE PUMP ROOM

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : MULTIPLEX SERVICES LLC.
CLIENT ADDRESS : P.O. BOX: 113503, ABU DHABI, UAE.
CONTACT PERSON : MR. VISHNUDETH PAMIDETH
SITE DETAILS : SHEIKH ZAYED DESRT LEARNING CENTRE,
AL AIN, U.A.E.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : MAY 2019
FREQUENCY OF CLEANING : EVERY YEAR
DATE OF NEXT CLEANING : MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire Water tank should be cleaned and disinfected minimum every one (1) year depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES