


# COMPLETION REPORT

For



تَفَاوُوق  
لإدارة المرافق  
t a f a w u q  
facility management

Client : Tafawuq Facilities Management

Contact Person: Mr. Kaishyap Shrestha  
FM Executive

Site Details : Marina Square,  
Al Reem Island, Abu Dhabi

Date : 20 July 2020



CRYSTALLINE  
ENVIRONMENTAL SERVICES

Crystalline Environmental  
Services

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uac.com](mailto:info@crystalline-uac.com)

[www.crystalline-uac.com](http://www.crystalline-uac.com)



## Sand Filter Media Replacement- A Zone, Bldg 12, A2

Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- A Zone, Bldg 12, A2

Before Photo



After Photo



Before Photo



After Photo




## Sand Filter Media Replacement- A Zone, Bldg 13, A1

Before Photo




After Photo



Before Photo




After Photo




## Sand Filter Media Replacement- A Zone, Bldg 13, A1

Before Photo



After Photo




---

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017  
E-mail: [info@crystalline-uae.com](mailto:info@crystalline-uae.com) | Website: [www.crystalline-uae.com](http://www.crystalline-uae.com)

## Sand Filter Media Replacement- A Zone, Bldg14, A3a


Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- A Zone, Bldg 15,A3b


Before Photo



After Photo



Before Photo




After Photo



## Sand Filter Media Replacement- B Zone, Bldg 11, B1


Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- B Zone, Bldg 10, B2

Before Photo




After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- C Zone, Bldg 8, CT1

Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- C Zone, Bldg 7, CT2

Before Photo



After Photo



Before Photo




After Photo




## Sand Filter Media Replacement- C Zone, Bldg 6, CT3


Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- C Zone, Bldg 5, CT4


Before Photo




After Photo



Before Photo




After Photo



## Sand Filter Media Replacement- C Zone, Bldg 4, CT5


Before Photo




After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- D Zone, Bldg 1, D1

Before Photo




After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- D Zone, Bldg 2, D2

Before Photo



After Photo



Before Photo



After Photo



## Sand Filter Media Replacement- D Zone, Bldg 3, D3

Before Photo



After Photo



Before Photo



After Photo



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CERTIFICATE

**CLIENT NAME** : TAFAWUQ FACILITIES MANAGEMENT

**CLIENT ADDRESS** : ABU DHABI, UAE

**CONTACT PERSON** : MR. KAISHYAP SHRESTHA

**SITE DETAILS** : MARINA SQUARE, ABU DHABI, UAE

**WORK DETAIL** : SAND FILTER MEDIA REPLACEMENT

**DATE OF SERVICE** : JUNE 2020



**CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES**