

# WATER TANK CLEANING & DISINFECTION COMPLETION REPORT

FOR



Client : National Contracting Company  
Limited.  
Contact Person: Mr. Vijay Ganapathy  
Project Co-Ordinator  
Site Details : NCC, Abu Dhabi, UAE.  
Date : 06 April 2019



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT


18182

|  |   |   |   |   |   |
|--|---|---|---|---|---|
| CUSTOMER: <u>NCL</u>   |   |   | CONTACT PERSON: <u>G. Karthik Keyan</u>                             |   |   |
| SITE DETAILS: <u>NCL store Room</u>  |   |   | CONTACT NO: <u>0508275059</u>                                       |   |   |
| TANK DETAILS: <u>fiber water Tank -01</u>  |   |   | LOCATION DETAILS: <u>store Room</u>                                 |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |
| <b>TYPE OF TANK</b>  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL                                  | <input checked="" type="checkbox"/> FRP TANK                        | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3   | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input type="checkbox"/> HALF                                       | <input checked="" type="checkbox"/> EMPTY                           |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS   | <input checked="" type="checkbox"/> MUD & SAND                      | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>  | <input checked="" type="checkbox"/> COVERED                         | <input type="checkbox"/> DAMAGED                                    | <input type="checkbox"/> NA   |
| <b>LADDER IN</b>   | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES  | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA  |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|  |   | <u>01-04-2019</u>   |   | <u>01-10-2019</u>   |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |   |   |   |
| 1. <u>lavada bio and plus</u> Quantity <u>100 ml</u>   |   |   |   |   |   |
| 2. _____ Quantity _____  |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder |   |   |   |   |   |
| <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials   |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |   |   |   |
| <u>water Tank cleaned and disinfected</u> <u>G. Karthi Keyan</u><br><u>0508275059</u>  |   |   |   |   |   |
| Crystalline Representative: <u>Bishal Rai</u>  |   |   | Signature:  |   |   |

Date of Cleaning: 01-04-2019

**PHOTOGRAPHS**  
**FRP WATER TANK- 01 (STORE ROOM)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

18183

|  |   |   |   |   |   |
|--|---|---|---|---|---|
| CUSTOMER: <i>NCC</i>   |   |   | CONTACT PERSON: <i>G. Karthi Koyan</i>                              |   |   |
| SITE DETAILS: <i>NCC store Room</i>  |   |   | CONTACT NO: <i>0508275059</i>                                       |   |   |
| TANK DETAILS: <i>fiber water Tank-02</i>   |   |   | LOCATION DETAILS: <i>store Room</i>                                 |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS  |   |   |   |   |   |
| <b>TYPE OF TANK</b>  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL                                  | <input checked="" type="checkbox"/> FRP TANK                        | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3   | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input type="checkbox"/> HALF                                       | <input checked="" type="checkbox"/> EMPTY                           |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS   | <input checked="" type="checkbox"/> MUD & SAND                      | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>  | <input checked="" type="checkbox"/> COVERED                         | <input type="checkbox"/> DAMAGED                                    | <input type="checkbox"/> NA   |
| <b>LADDER IN</b>   | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES  | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA  |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|  |   | <i>01-04-2019</i>   |   | <i>01-10-2019</i>   |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |   |   |   |
| 1. <i>Cavala bio and plus</i> Quantity <i>100 ml</i>   |   |   |   |   |   |
| 2. _____ Quantity _____  |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |   |   |   |
| <i>water Tank deamed and disinfected</i>   |   |   |   |   |   |
| <i>G. Karthi Koyan.<br/>0508275059.</i>  |   |   |   |   |   |
| Crystalline Representative: <i>Bishal Rai</i>  |   |   | Signature: <i>[Signature]</i>                                       |   |   |




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-04-2019

**PHOTOGRAPHS**  
**FRP WATER TANK – 02 (STORE ROOM)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

18184

|  |   |   |   |   |   |
|--|---|---|---|---|---|
| CUSTOMER: <i>NCC</i>   |   |   | CONTACT PERSON: <i>G. Karthikeyan</i>                               |   |   |
| SITE DETAILS: <i>NCC store Room</i>  |   |   | CONTACT NO: <i>050 82 75 059</i>                                    |   |   |
| TANK DETAILS: <i>Fiber water tanks</i>   |   |   | LOCATION DETAILS: <i>store Room</i>                                 |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS  |   |   |   |   |   |
| <b>TYPE OF TANK</b>  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL                                  | <input checked="" type="checkbox"/> FRP TANK                        | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL  | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3   | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF  | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY  | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS   | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS   | <input checked="" type="checkbox"/> MUD & SAND                      | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND   | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>  |   | <input checked="" type="checkbox"/> COVERED   | <input type="checkbox"/> DAMAGED <input type="checkbox"/> NA        |
| <b>LADDER IN</b>   | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                             | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |   |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|  |   | <i>01-04-2019</i>   |   | <i>01-10-2019</i>   |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |   |   |   |
| 1. <i>Carbo bio and plus</i> Quantity <i>100 ml</i>  |   |   |   |   |   |
| 2. _____ Quantity _____  |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |   |   |   |
| <i>water Tank cleaned and disinfected</i>  |   |   |   |   |   |
| Crystalline Representative: <i>Bishal Rai</i>  |   |   | Signature: _____  |   |   |



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-04-2019

**PHOTOGRAPHS**  
**FRP WATER TANK – 03 (STORE ROOM)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : NATIONAL CONTRACTING COMPANY LIMITED.

CLIENT ADDRESS : P.O. BOX: 40327, ABU DHABI, UAE.

CONTACT PERSON : MR. VIJAY GANAPATHY.

SITE DETAILS : NCC, ABU DHABI.

DETAILS : WATER TANK CLEANING


DATE OF CLEANING : APRIL 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : OCTOBER 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES