

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Manhole & Drain Line Cleaning

Date: **30 November 2019**
Client Name: **Sinyar - Presidential Palace**
Contact Person: **Mr. Ankit Rawat**
Designation: **Third Party Services Supervisor**
Site Detail: **Presidential Palace**





CRYSTALLINE ENVIROMENTAL SERVICES

2655

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW	CONTACT PERSON: MR ANKIT
SITE DETAILS: PRESIDENTIAL PALACE	CONTACT NUMBER: 0564208324
NAME OF MANHOLE: FLOOR DRAIN	LOCALISQTION: PMCW - MAJILIS
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

<input type="checkbox"/> MANHOLE	<input type="checkbox"/> UNDERGROUND DRAINAGE PIPE	<input type="checkbox"/> GULLY TRAP	<input type="checkbox"/> GREASE TRAP
<input type="checkbox"/> DRAINAGE PIPE	<input type="checkbox"/> APPARENT DRAINAGE PIPE	<input checked="" type="checkbox"/> FLOOR DRAIN <input type="checkbox"/> EMBEDDED DRAINAGE PIPE	

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

<input type="checkbox"/> LITTLE DIRTY	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> SLIME	<input type="checkbox"/> GREASE	<input type="checkbox"/> ROOT	<input type="checkbox"/> SAND	<input type="checkbox"/> MOULDS
<input type="checkbox"/> OBSTRUCT	<input type="checkbox"/> BLOCK	<input type="checkbox"/> FLUENT FLOW	<input checked="" type="checkbox"/> LOW FLOW	<input type="checkbox"/> ANOTHER: _____	

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE CLEARED THE ABOVE MENTIONED BY USE OF PRESSURE MACHINE.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

<input type="checkbox"/> LITTLE CLEAN	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> VERY CLEAN	<input type="checkbox"/> FLUENT FLOW	<input type="checkbox"/> LOW FLOW	<input type="checkbox"/> UNBLOCK
	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					2
NUMBER OF MANHOLE BLOCKED					

ACCESS

<input type="checkbox"/> LADDER IN	<input type="checkbox"/> NO LADDER		
MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	02-11-2019	

"REACTIVE MAINTENANCE" CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> PRESSURE MACHINE	<input type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> MULTIGAS DETECTEUR	<input checked="" type="checkbox"/> INLET WATER HOSE
<input checked="" type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER	<input type="checkbox"/> VENTILATION FAN	<input type="checkbox"/> CLEANING MAT
<input type="checkbox"/> LED LIGHTS	<input type="checkbox"/> PLASTICS ROLL	<input type="checkbox"/> PLASTICS BAGS	<input checked="" type="checkbox"/> SUITABLE PPE
<input type="checkbox"/> TRIPOD	<input type="checkbox"/> AIR REPAIR 7D-A	<input type="checkbox"/> DEGREASER CHEMICAL	<input type="checkbox"/> LADDER

COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY

Crystalline representative: FRANK	Signature:
Customer/Customer representative: ISMAIL	Signature:



CRYSTALLINE ENVIROMENTAL SERVICES

2656

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>	CONTACT PERSON: <u>MR ANKIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0564208724</u>
NAME OF MANHOLE: <u>STORM DRAIN LINE</u>	LOCALISQTION: <u>PMCW - G F</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP
 DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

STORM DRAIN LINE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD
 BIOFILMS SLIME GREASE ROOT SAND MOULDS
 OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: STONES.

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED THE DEBRISES, STONES, AND SAND THAT TRAPPED INTO THE ABOVE MENTIONED BY USE OF PRESSURE MACHINE
MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

<u>CLEARED</u>	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>02/11/2019</u>	

"REACTIVE MAINTENANCE"

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE
 EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT
 LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE
 TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY.

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>ISMAIL</u>	Signature:




CRYSTALLINE ENVIROMENTAL SERVICES

2657

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564208324	
NAME OF MANHOLE: FLOOR DRAIN LINE		LOCALISQTION: PPP3	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> BSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: (MUD)			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED MUD, SAND FROM THE ABOVE MENTIONED AND CLEARED PROPERLY			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			4
NUMBER OF MANHOLE BLOCKED			4
ACCESS			
<input type="checkbox"/> LADDER IN <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	02/11/2019		
CHEMICALS AND EQUIPMENTS USED			
<input checked="" type="checkbox"/> PRESSURE MACHINE <input checked="" type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input type="checkbox"/> INLET WATER HOSE			
<input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input checked="" type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ANKIT		Signature:	

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Floor drain		Location: PMSG- (VIP security gate)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input checked="" type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input checked="" type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input checked="" type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We cleared the above mentioned by use of presure machine (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input checked="" type="checkbox"/> Unblock			
Number of Cleaned			
Manhole:	Gully Trap:	Storm Water:	Drainage: 6 Total: 6
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		03 November 2019	
		Next Cleaning Date	
		03 May 2020	
Crystalline Representative		Customer Representative	
			



CRYSTALLINE ENVIRONMENTAL SERVICES

1750



MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT



CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564208324	
NAME OF MANHOLE: FLOOR DRAINAGE		LOCALISATION: PM 8/W LG P.0339a	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> INDUSTRIAL			
SEWAGE & GREASE TRAP TANK PART OF DRAINAGE			
<input checked="" type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input checked="" type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: MUD			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED MUD AND GREASE FROM THE ABOVE MENTIONED AND CLEANED PROPERLY			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER DRAINAGE
NUMBER OF MANHOLE CLEANED	2		
NUMBER OF MANHOLE BLOCKED			2
ACCESS			
<input type="checkbox"/> LADDER IN		<input checked="" type="checkbox"/> NO LADDER	
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE	
	03/11/2019	19/OCT/2019	
CHEMICALS AND EQUIPMENTS USED			
<input checked="" type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input checked="" type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE			
<input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input checked="" type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input checked="" type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE ^{CLEANED} THE ABOVE MENTIONED PROPERLY, THEY SHOULD STOP DUMPING TISSUES INSIDE TOILET			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative:		Signature: 03/11/19	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

NOTE: UNDER OBSERVATION FOR 3 Days. And

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: STORM WATER Manhole		Location: PMSG- (VIP-security gate)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We cleaned the above mentioned by use of pressure machine (picture not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole:	Gully Trap:	Storm Water: 6	Drainage: Total: 6
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input checked="" type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		04 November 2019	
		Next Cleaning Date	
		04 May 2020	
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: RCC_ STORM WATER Manhole		Location: PMSG- (VIP security gate)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We removed sand and mud from the above mentioned well cleaned.			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole:	Gully Trap:	Storm Water: 8	Drainage: Total: 8
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		05 November 2019	
Next Cleaning Date			
05 May 2020			
Crystalline Representative		Customer Representative	
			



CRYSTALLINE ENVIROMENTAL SERVICES

2601

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER:	
NAME OF MANHOLE: FLOOR DRAIN		LOCALISQTION: MAIN BUILDING GF #16	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE MALE, FEMALE TOILET & JANITOR'S ROOM			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: _____			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE CLEANED THE ABOVE MENTIONED PROPERLY			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER DRAINAGE
NUMBER OF MANHOLE CLEANED			1
NUMBER OF MANHOLE BLOCKED			1
ACCESS			
<input type="checkbox"/> LADDER IN <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		DRAINAGE CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
GULLY TRAP CLEANED		ALL DISINFECTED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	06/11/2019		
CHEMICALS AND EQUIPMENTS USED			
<input checked="" type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE			
<input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE CLEANED THE ABOVE MENTIONED PROPERLY			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ROBIN JOHNY		Signature: 6/11/19	



CRYSTALLINE ENVIROMENTAL SERVICES

2663

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW	CONTACT PERSON: MR ANKIT
SITE DETAILS: PRESIDENTIAL PALACE	CONTACT NUMBER: 0564208324
NAME OF MANHOLE: SEWAGE	LOCALISQTION: PP 3 LG 0105
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: FECES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE CLEANED THE ABOVE MENTIONED PROPERLY

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	1				1
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	06/11/2019	06/05/2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT


LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE



TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER


COMMENTS AND RECOMMENDATION: WE CLEANED THE ABOVE MENTIONED PROPERLY. THIS ABOVE MENTIONED SHOULD BE ALWAYS CLOSED BY KHASHANEH AFTER THEY OPEN IT

Crystalline representative: FRANK	Signature:
Customer/Customer representative:	Signature:



Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Floor gully, storm water and sewage		Location: PSGA (GATE A)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input checked="" type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We removed sand, mud from the above and cleaned y			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 3		Gully Trap:	
Storm Water: 1		Drainage: 4	
Total: 7			
Number of Blocked			
Manhole:		Gully Trap:	
Storm Water:		Drainage:	
Total:			
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		07 November 2019	
		Next Cleaning Date	
		07 May 2020	
Crystalline Representative		Customer Representative	
			


Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Floor gully, storm water and sewage		Location: PSGB (GATE B)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input checked="" type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We removed sand and mud from the above mentioned and cleaned properly			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 2		Gully Trap:	
Storm Water: 1		Drainage: 4	
Total: 7			
Number of Blocked			
Manhole:		Gully Trap:	
Storm Water:		Drainage:	
Total:			
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		07 November 2019	
Next Cleaning Date			
07 May 2020			
Crystalline Representative		Customer Representative	
			


Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Manhole, sewerage and gully trap		Location: PSMA (MILITARY ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input checked="" type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We removed sand and cleared the above mentioned properly			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 10	Gully Trap: 13	Storm Water: 7	Drainage: Total: 30
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		10 November 2019	
Next Cleaning Date			
10 May 2020			
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Manhole and gully trap		Location: PSMA (MILITARY ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input checked="" type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Comments			
We removed mud and cleared the above mentioned properly (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input checked="" type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 5	Gully Trap: 5	Storm Water: 5	Drainage: Total: 15
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		11 November 2019	
		Next Cleaning Date	
		11 May 2020	
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Floor drain line		Location: PSMA (MILITARY ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input type="checkbox"/> Manhole <input checked="" type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input checked="" type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We cleared and cleaned the above mentioned properly (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole:	Gully Trap:	Storm Water:	Drainage: 50 Total: 50
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		12 November 2019	
		Next Cleaning Date	
		12 May 2020	
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Manhole and gully trap		Location: PSSA(STAFF ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input checked="" type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input checked="" type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Comments			
We removed mud from the above mentioned and cleared properly (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input checked="" type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 13	Gully Trap: 9	Storm Water: 4	Drainage: Total: 26
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		13 November 2019	
		Next Cleaning Date	
		13 May 2020	
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Manhole, sewerage and gully trap		Location: PSSA(STAFF ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input checked="" type="checkbox"/> Manhole <input checked="" type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input checked="" type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Comments			
We removed mud and cleared the above mentioned properly (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input checked="" type="checkbox"/> Unblock			
Number of Cleaned			
Manhole: 8	Gully Trap: 12	Storm Water: 7	Drainage: Total: 27
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		16 November 2019	
		Next Cleaning Date	
		16 May 2020	
Crystalline Representative		Customer Representative	
			

Customer: Sinyar - Presidential Palace		Contact Person: Mr. Ankit Rawat	
Site: Presidential Palace		Contact Number: 0	
Description: Floor drain line		Location: PSSA(STAFF ACCOMMODATION)	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Part Of Drainage			
<input type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
Condition Of Manhole, Gully Trap, Drainage before cleaning			
<input type="checkbox"/> Little Dirty <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow Another:			
Manhole Blocked		Gully Trap Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Blocked		All Blocked	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Comments			
We cleared and cleaned the above mentioned properly (pictures not allowed)			
Condition Of Manhole, Gully Trap, Drainage after cleaning			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
Number of Cleaned			
Manhole:	Gully Trap:	Storm Water:	Drainage: 48 Total: 48
Number of Blocked			
Manhole:	Gully Trap:	Storm Water:	Drainage: Total:
Access		Manhole and Gully Trap Cover	
<input type="checkbox"/> Larder In <input type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
Manhole Cleaned		Gully Trap Cleaned	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Drainage Cleaned		All Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Presure Machine <input checked="" type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
Last Cleaning Date		Current Cleaning Date	
-		17 November 2019	
Next Cleaning Date			
17 May 2020			
Crystalline Representative		Customer Representative	
			



CRYSTALLINE ENVIROMENTAL SERVICES

2667

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>CLAW</u>		CONTACT PERSON: <u>MR ANKIT</u>	
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>		CONTACT NUMBER: <u>0562208324</u>	
NAME OF MANHOLE: <u>DRAIN LINE</u>		LOCALISQTION: <u>TOP ROOF PMMS</u>	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: <u>STONES</u>			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: <u>WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED</u>			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input checked="" type="checkbox"/> UNBLOCK			
		MANHOLE	GULLY TRAP
NUMBER OF MANHOLE CLEANED			
NUMBER OF MANHOLE BLOCKED			
		STORM WATER	DRAINAGE
			6
			6
ACCESS			
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> <u>CLEARED</u> <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE CLEANED		ALL DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	<u>19/11/2020</u>		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE		<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT	
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE		<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER	
COMMENTS AND RECOMMENDATION: <u>WE CLEARED THE ABOVE MENTI-</u>			
Crystalline representative: <u>FRANK</u>		Signature:	
Customer/Customer representative: <u>ANKIT</u>		Signature:	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2668

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW	CONTACT PERSON: MR ANKIT
SITE DETAILS: PRESIDENTIAL PALACE	CONTACT NUMBER: 0564208324
NAME OF MANHOLE: DRAIN LINE	LOCALISQION: TOP ROOF PMM13
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART 10

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: STONES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				5	5
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	19/11/2019	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE (CLEARED) THE ABOVE MENTIONED PROPERLY

Crystalline representative: FRANK

Signature:

Customer/Customer representative: ANKIT

Signature:



CRYSTALLINE ENVIROMENTAL SERVICES

2669

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>	CONTACT PERSON: <u>MR ANKIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0564208324</u>
NAME OF MANHOLE: <u>DRAIN LINE</u>	LOCALISQION: <u>TOP ROOF PMM13</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE PART 5

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: STONES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED PROPERLY

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED				5	5

ACCESS

LADDER IN (CLEARED) NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>19/11/2019</u>	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>Ankur Patel</u>	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2676

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR AMKI	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564208324	
NAME OF MANHOLE: STORM WATER		LOCALISQTION: P P 3 - PARKING AREA	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE			
<input checked="" type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD <input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS <input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: _____			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED MUD, SAND FROM THE ABOVE MENTIONED AND CLEANED PROPERLY			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input checked="" type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			6
NUMBER OF MANHOLE BLOCKED			6
			6
ACCESS			
<input type="checkbox"/> LADDER IN <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE CLEANED		ALL DISINFECTED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	19/11/2019	19/05/2020	
CHEMICALS AND EQUIPMENTS USED			
<input checked="" type="checkbox"/> PRESSURE MACHINE <input checked="" type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE <input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT <input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE <input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE CLEANED AND CLEARED THE ABOVE MENTIONED PROPERLY.			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ANWER PANA -		Signature:	



CRYSTALLINE ENVIROMENTAL SERVICES

2670

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564 208324	
NAME OF MANHOLE: DRAW LINE		LOCALISQTION: Top Roof Pmm13	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE PART 8			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> RUST
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> SLIME	<input type="checkbox"/> GREASE	<input type="checkbox"/> ROOT
<input type="checkbox"/> OBSTRUCT	<input type="checkbox"/> BLOCK	<input type="checkbox"/> FLUENT FLOW	<input type="checkbox"/> LOW FLOW
<input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> ANOTHER: STONES			
MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO
COMMENTS: WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED.			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN	<input type="checkbox"/> CLEAN	<input type="checkbox"/> VERY CLEAN	<input checked="" type="checkbox"/> FLUENT FLOW
		<input type="checkbox"/> LOW FLOW	<input checked="" type="checkbox"/> UNBLOCK
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			DRAINAGE
NUMBER OF MANHOLE BLOCKED			TOTAL
			5
			5
ACCESS			
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> NO LADDER			
MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	20/11 2019		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE	<input type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> MULTIGAS DETECTEUR	<input checked="" type="checkbox"/> INLET WATER HOSE
<input type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER	<input type="checkbox"/> VENTILATION FAN	<input type="checkbox"/> CLEANING MAT
<input type="checkbox"/> LED LIGHTS	<input type="checkbox"/> PLASTICS ROLL	<input checked="" type="checkbox"/> PLASTICS BAGS	<input checked="" type="checkbox"/> SUITABLE PPE
<input type="checkbox"/> TRIPOD	<input type="checkbox"/> AIR REPAIR 7D-A	<input type="checkbox"/> DEGREASER CHEMICAL	<input type="checkbox"/> LADDER
COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ANKIT		Signature:	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2671

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>	CONTACT PERSON: <u>MR ANKIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0564208324</u>
NAME OF MANHOLE: <u>DRAIN LINE</u>	LOCALISQTION: <u>TOP ROOF PMM13</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART 7

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: STONES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED PROPERLY.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				7	7
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>20/11/2019</u>	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY.

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>Shou</u>	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2672

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>CAW</u>	CONTACT PERSON: <u>MR AMKIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0562208324</u>
NAME OF MANHOLE: <u>DRAIN LINE</u>	LOCALISQTION: <u>TOP ROOF PMMB</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART 2

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: STONES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE ~~CA~~ STONES, SAND WERE REMOVED FROM THE ABOVE MENTIONED AND CLEARED.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				8	8
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>20/11/2019</u>	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: THE ABOVE MENTIONED ~~WERE~~ ARE CLEARED PROPERLY

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>AMKIT</u>	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2673

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>		CONTACT PERSON: <u>MR ANKIT</u>			
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>		CONTACT NUMBER: <u>0564208224</u>			
NAME OF MANHOLE: <u>DRAIN LINE</u>		LOCALISQION: <u>TOP ROOF PMM13</u>			
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL					
PART OF DRAINAGE					
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP <input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE					
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING					
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD <input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS <input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: <u>STONES</u>					
MANHOLE BLOCKED		GULLY TRAP BLOCKED			
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO			
DRAINAGE BLOCKED		ALL BLOCKED			
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO			
COMMENTS: <u>WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED</u>					
MANHOLE AND GULLY TRAP COVER: <input type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input checked="" type="checkbox"/> ADAPTED					
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING					
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input checked="" type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK					
	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				8	8
NUMBER OF MANHOLE BLOCKED					
ACCESS					
<input type="checkbox"/> LADDER IN <u>CLEARED</u> <input type="checkbox"/> NO LADDER					
MANHOLE CLEANED		GULLY TRAP CLEANED		DRAINAGE CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES					
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>20/11/2019</u>			
CHEMICALS AND EQUIPMENTS USED					
<input type="checkbox"/> PRESSURE MACHINE		<input type="checkbox"/> JETTING MACHINE		<input type="checkbox"/> MULTIGAS DETECTEUR	
<input type="checkbox"/> EXTENTION CORDS		<input type="checkbox"/> VACCUM CLEANER		<input type="checkbox"/> VENTILATION FAN	
<input type="checkbox"/> LED LIGHTS		<input type="checkbox"/> PLASTICS ROLL		<input checked="" type="checkbox"/> PLASTICS BAGS	
<input type="checkbox"/> TRIPOD		<input type="checkbox"/> AIR REPAIR 7D-A		<input type="checkbox"/> DEGREASER CHEMICAL	
				<input checked="" type="checkbox"/> INLET WATER HOSE	
				<input type="checkbox"/> CLEANING MAT	
				<input checked="" type="checkbox"/> SUITABLE PPE	
				<input type="checkbox"/> LADDER	
COMMENTS AND RECOMMENDATION: <u>THE ABOVE MENTIONED ARE CLEARED PROPERLY, NOTE ONE LINE IS NOT CLEARED PROPERLY.</u>					
Crystalline representative: <u>FRANK</u>				Signature: <u>[Signature]</u>	
Customer/Customer representative: <u>Ankit</u>				Signature: <u>[Signature]</u>	



CRYSTALLINE ENVIROMENTAL SERVICES

2674

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564208324	
NAME OF MANHOLE: DRAIN LINE		LOCALISQTION: TOP ROOF PMMB	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART 6			
PART OF DRAINAGE			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: STONES			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED			
MANHOLE AND GULLY TRAP COVER: <input type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input checked="" type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER DRAINAGE
NUMBER OF MANHOLE CLEANED			4
NUMBER OF MANHOLE BLOCKED			4
ACCESS			
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> CLEARED <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE CLEANED		ALL DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	20/11/2019		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE			
<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE CLEARED THE ABOVE MENTIONED PROPERLY			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ANKIT		Signature:	



CRYSTALLINE ENVIROMENTAL SERVICES

2675

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>		CONTACT PERSON: <u>MR ANKT</u>	
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>		CONTACT NUMBER: <u>0562208324</u>	
NAME OF MANHOLE: <u>DRAIN LINE</u>		LOCALISQTION: <u>TOP ROOF PMM13</u>	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE <u>PART 12</u>			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: <u>STONES</u>			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: <u>WE REMOVED STONES, SAND FROM THE ABOVE MENTIONED AND CLEARED PROPERLY.</u>			
MANHOLE AND GULLY TRAP COVER: <input type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input checked="" type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input checked="" type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	TOTAL
NUMBER OF MANHOLE CLEANED			<u>5</u>
NUMBER OF MANHOLE BLOCKED			<u>5</u>
ACCESS			
<input type="checkbox"/> LADDER IN		<input type="checkbox"/> NO LADDER	
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	<u>20/11/2019</u>		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE			
<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: <u>WE CLEARED ABOVE MENTIONED PROPERLY BUT ONE LINE IS NOT CLEARED PROPERLY.</u>			
Crystalline representative: <u>FRANK</u>		Signature: <u>[Signature]</u>	
Customer/Customer representative: <u>ANKIT RAJWAJ</u>		Signature: <u>[Signature]</u>	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com

E-mail: info@crystalline-uae.com

Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2677

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0504208324	
NAME OF MANHOLE: DRAIN LINE		LOCALISQTION: PP 3- PARKING AREA	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE DRAIN LINE			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input checked="" type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: MUD & STONE			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED MUD, STONES FROM THE ABOVE MENTIONED AND CLEARED PROPERLY.			
MANHOLE AND GULLY TRAP COVER: <input type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			
NUMBER OF MANHOLE BLOCKED			
ACCESS			
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> (CLEARED) <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	20/11/2019		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input type="checkbox"/> INLET WATER HOSE			
<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE BE CLEANED AND (CLEARED) CLEARED THE ABOVE MENTIONED PROPERLY.			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative: ANKIT RAJAN		Signature:	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2680

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW	CONTACT PERSON: MR ANKIT
SITE DETAILS: PRESIDENTIAL PALACE	CONTACT NUMBER: 0564208324
NAME OF MANHOLE: FLOOR DRAIN	LOCALISQTION: PMCW - 1ST FLOOR
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: UNPLEASANT @ DOUR

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: THE ABOVE MENTIONED WAS FLUSHED BY USE OF PRESSURE MACHINE AND CLEANED PROPERLY.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				1	1
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	23/11/19	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: THE ABOVE MENTIONED WAS CLEANED PROPERLY

Crystalline representative: FRANK	Signature:
Customer/Customer representative: Anwar	Signature:

CLEANER WATER GREENER TOMORROW

0566172816

Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2678

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW		CONTACT PERSON: MR ANKIT	
SITE DETAILS: PRESIDENTIAL PALACE		CONTACT NUMBER: 0564208324	
NAME OF MANHOLE: DRAIN LINE		LOCALISQTION: DP 3 - PARKING	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE DRAIN LINE			
<input type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: STONES			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
COMMENTS: WE REMOVED MUD, STONES AND CLEARED THE ABOVE MENTIONED AND CLEANED PROPERLY			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input checked="" type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			
NUMBER OF MANHOLE BLOCKED			
ACCESS			
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> NO LADDER CLEARED			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	23/11/2019		
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input type="checkbox"/> INLET WATER HOSE			
<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: WE CLEANED AND CLEARED THE ABOVE MENTIONED PROPERLY.			
Crystalline representative: FRANK		Signature:	
Customer/Customer representative:		Signature:	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2610

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: QAW	CONTACT PERSON: MR ANKIT
SITE DETAILS: PRESIDENTIAL PALACE	CONTACT NUMBER: 0564208324
NAME OF MANHOLE: DRAIN LINE	LOCALISQTION: PP4, PARKING AREA
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP
 DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD
 BIOFILMS SLIME GREASE ROOT SAND MOULDS
 OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: SAND

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED SAND FROM THE ABOVE MENTIONED AND CLEANED PROPERLY

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN LADDER CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	25/11/2019	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE
 EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT
 LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE
 TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEANED AND A THE ABOVE MENTIONED PROPERLY

Crystalline representative: FRANK	Signature:
Customer/Customer representative: ANKIT RAJWAJ	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017



CRYSTALLINE ENVIROMENTAL SERVICES

2611

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>QAW</u>	CONTACT PERSON: <u>MR ANKIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0564208324</u>
NAME OF MANHOLE: <u>DRAINE</u>	LOCALISQTION: <u>PPL PARKING AREA</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE DRAIN LINE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: SAND

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED SAND FROM THE ABOVE MENTIONED ANI (CLEAR) PROPERLY

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEAR NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>26/11/2019</u>	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEARED ANI (CLEANED) THE ABOVE MENTIONED PROPERLY

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>ANKIT</u>	Signature:

CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIROMENTAL SERVICES

2681

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>RAW</u>	CONTACT PERSON: <u>MR AMRIT</u>
SITE DETAILS: <u>PRESIDENTIAL PALACE</u>	CONTACT NUMBER: <u>0564208324</u>
NAME OF MANHOLE: <u>DRAIN LINE</u>	LOCALISQTION: <u>P P 4, PARKING AREA</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

DRAIN LINE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: SAND

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: WE REMOVED SAND FROM THE ABOVE MENTIONED AND CLEARED

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN CLEARED NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

SERVICES OF DATES

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>30/11/2019</u>	

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: WE CLEANED AND CLEARED THE ABOVE MENTIONED PROPERLY

Crystalline representative: <u>FRANK</u>	Signature:
Customer/Customer representative: <u>AMRIT</u>	Signature: