

**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**



Completion Report for  
**Manhole & Drain Line Cleaning**

Date: **02 February 2020**  
Client Name: **Sinyar - Presidential Palace**  
Contact Person: **Mr. Ankit Rawat**  
Designation: **Third Party Services Supervisor**  
Site Detail: **QAW- Presidential Palace**





---

**Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017**  
**E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com**

<b>Customer:</b> Sinyar - Presidential Palace		<b>Contact Person:</b> Mr. Ankit	
<b>Site:</b> Presidential Palace, Abu Dhabi		<b>Contact Number:</b> 0564208324	
<b>Description:</b> Roof Top storm drain		<b>Location:</b> Btw Main MAJLIS & PMPW GF (ARCADE)	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Part Of Drainage</b>			
<input type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
<b>Condition Of Manhole, Gully Trap, Drainage before cleaning</b>			
<input type="checkbox"/> Little Dirty <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input checked="" type="checkbox"/> Obstruct <input type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <b>Another:</b> Debris			
<b>Manhole Blocked</b>		<b>Gully Trap Blocked</b>	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drainage Blocked</b>		<b>All Blocked</b>	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Comments</b>			
The above mentioned roof Top storm water drain are cleared properly by pressuring water and removed all the instructions and disposed.			
<b>Condition Of Manhole, Gully Trap, Drainage after cleaning</b>			
<input type="checkbox"/> Little Clean <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input checked="" type="checkbox"/> Fluent Flow <input type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
<b>Number of Cleaned</b>			
<b>Manhole:</b>	<b>Gully Trap:</b> None	<b>Storm Water:</b>	<b>Drainage:</b> 22 no's
			no's
<b>Number of Blocked</b>			
<b>Manhole:</b> None	<b>Gully Trap:</b> None	<b>Storm Water:</b> None	<b>Drainage:</b> 1 no <b>Total:</b> 1 no
<b>Access</b>		<b>Manhole and Gully Trap Cover</b>	
<input type="checkbox"/> Larder In <input checked="" type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
<b>Manhole Cleaned</b>		<b>Gully Trap Cleaned</b>	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Drainage Cleaned</b>		<b>All Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Equipments Used</b>			
<input type="checkbox"/> Pressure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Rool <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		02 December 2020	
<b>Next Cleaning Date</b>			
02 June 2021			
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			



<b>Customer:</b> Sinyar - Presidential Palace		<b>Contact Person:</b> Mr. Ankit	
<b>Site:</b> Presidential Palace, Abu Dhabi		<b>Contact Number:</b> 0564208324	
<b>Description:</b> Roof Top storm drain		<b>Location:</b> Btw Main MAJLIS & PMPW GF (ARCADE)	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Part Of Drainage</b>			
<input type="checkbox"/> Manhole <input type="checkbox"/> Gully Trap <input type="checkbox"/> Grease Trap <input type="checkbox"/> Drainage Pipe <input type="checkbox"/> Underground Drainage Pipe <input type="checkbox"/> Apparent Drainage Pipe <input checked="" type="checkbox"/> Embedded Drainage Pipe			
<b>Condition Of Manhole, Gully Trap, Drainage before cleaning</b>			
<input type="checkbox"/> Little Dirty <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Rust <input type="checkbox"/> Sediments <input type="checkbox"/> Mud <input type="checkbox"/> Biofilms <input type="checkbox"/> Slime <input type="checkbox"/> Grease <input type="checkbox"/> Root <input type="checkbox"/> Sand <input type="checkbox"/> Moulds <input checked="" type="checkbox"/> Obstruct <input checked="" type="checkbox"/> Block <input type="checkbox"/> Fluent Flow <input checked="" type="checkbox"/> Low Flow <b>Another:</b> Blocked.			
<b>Manhole Blocked</b>		<b>Gully Trap Blocked</b>	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drainage Blocked</b>		<b>All Blocked</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Comments</b>			
The above mentioned roof top storm drain is blocked. (1 no).			
<b>Condition Of Manhole, Gully Trap, Drainage after cleaning</b>			
<input type="checkbox"/> Little Clean <input type="checkbox"/> Clean <input type="checkbox"/> Very Clean <input type="checkbox"/> Fluent Flow <input checked="" type="checkbox"/> Low Flow <input type="checkbox"/> Unblock			
<b>Number of Cleaned</b>			
<b>Manhole:</b>	<b>Gully Trap:</b> None	<b>Storm Water:</b>	<b>Drainage:</b>
			<b>Total:</b>
<b>Number of Blocked</b>			
<b>Manhole:</b> None	<b>Gully Trap:</b> None	<b>Storm Water:</b> None	<b>Drainage:</b> 1 no
			<b>Total:</b> 1 no
<b>Access</b>		<b>Manhole and Gully Trap Cover</b>	
<input type="checkbox"/> Larder In <input checked="" type="checkbox"/> No Larder		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> Blocked <input type="checkbox"/> Adapted	
<b>Manhole Cleaned</b>		<b>Gully Trap Cleaned</b>	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Drainage Cleaned</b>		<b>All Disinfected</b>	
<input type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Equipments Used</b>			
<input type="checkbox"/> Presure Machine <input type="checkbox"/> Jetting Machine <input type="checkbox"/> Multigas Detecteur <input type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Inlet Water Hose <input type="checkbox"/> Extension Cords <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Ventilation Fan <input type="checkbox"/> Cleaning Mat <input type="checkbox"/> Air Repair 7D-A <input type="checkbox"/> Plastics Roof <input checked="" type="checkbox"/> Plastics Bags <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Tripod <input type="checkbox"/> Ladder			
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		02 December 2020	
		<b>Next Cleaning Date</b>	
		02 June 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## MANHOLE & DRAIN LINE CLEANING

**CLIENT NAME** : SINYAR - PRESIDENTIAL PALACE  
**CONTACT PERSON** : MR. ANKIT RAWAT  
**DESIGNATION** : THIRD PARTY SERVICES SUPERVISOR  
**SITE DETAILS** : QAW- PRESIDENTIAL PALACE  
**DETAILS** : MANHOLE & DRAIN LINE CLEANING  
**DATE OF CLEANING** : 02 DECEMBER 2020  
**FREQUENCY OF CLEANING** : HALF YEARLY  
**DATE OF NEXT CLEANING** : 02 MAY 2021

*The above system is thoroughly cleaned and all the solids and debris removed and disposed.*

*Regular, preventive maintenance will ensure removal of solids which settle at the bottom, reducing its capacity and efficiency.*



*Jasman Pinto*

## CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES