

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

Water Tank Cleaning & Disinfection

Date: **10 August 2020**
Client Name: **Al Seer Marine**
Contact Person: **Mr. Ayodeji Quadri**
Designation: **Supervisor**
Site Detail: **Al Seer Marine - Abu Dhabi**





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

18152

| | | | |
|--|---|--|---|
| CUSTOMER: <u>AL Suez Marine</u> | | CONTACT PERSON: <u>M.R. Ayodeji</u> | |
| SITE DETAILS: <u>Bot Building Mussafah</u> | | CONTACT NO: <u>0561949496</u> | |
| TANK DETAILS: <u>Sinterax Water Tank 2</u> | | LOCATION DETAILS: <u>ground Floor</u> | |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | |
| <input type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED |
| <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC | <input type="checkbox"/> CONCRETE COATED | <input checked="" type="checkbox"/> POLYURETHANE |
| <input type="checkbox"/> OTHERS | | | |
| SIZE OF TANK | | QUANTITY OF WATER | |
| M3 <u>3000</u> USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | CONDITION OF WATER TANK AFTER CLEANING | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> DIRTY |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> MOULDS |
| <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | |
| <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA | |
| LADDER IN | | LADDER OUT | |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | | |
| LEAKS | | DRAIN LINE | |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| VALVES | | FLOAT VALVE | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| TANK CLEANED | | TANK DISINFECTED | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | |
| PIPES DISINFECTED | | | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA | | | |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | |
| | | <u>09/08/2020</u> | |
| | | NEXT CLEANING DATE | |
| | | <u>09/02/2021</u> | |
| CHEMICALS & EQUIPMENTS USED | | | |
| 1. <u>Carela bio and plus</u> Quantity <u>100 ML</u> | | | |
| 2. _____ Quantity _____ | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | |
| COMMENTS AND RECOMMENDATION: | | | |
| <u>Mention water Tank Cleaning and Disinfected</u> | | | |
| Crystalline representative: <u>Bishal</u> | | Signature: _____ | |
| Customer/Customer representative: _____ | | Signature: _____ | |



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

18157

| | | | | | |
|--|---|---|---|---|---|
| CUSTOMER: <u>AL Seer Marine</u> | | | CONTACT PERSON: <u>M:R Ayodeji</u> | | |
| SITE DETAILS: <u>Bot Building Mussafah</u> | | | CONTACT NO: <u>0561944496</u> | | |
| TANK DETAILS: <u>RCC water Tank-1</u> | | | LOCATION DETAILS: <u>ground floor</u> | | |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | <u>10000 Gals</u> | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF |
| <input type="checkbox"/> EMPTY | | | | | |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | | | | | |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO <input type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <u>10/08/2020</u> | | <u>10/02/2021</u> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <u>Carla bio and plus</u> Quantity <u>200 ML</u> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS AND RECOMMENDATION: | | | | | |
| <u>Mention water Tank Cleaning and Disinfected</u> | | | | | |
| Crystalline representative: <u>Bishal</u> | | | Signature: _____ | | |
| Customer/Customer representative: | | | Signature: _____ | | |

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : AL SEER MARINE
CONTACT PERSON : MR. AYODEJI QUADRI
DESIGNATION : SUPERVISOR
SITE DETAILS : AL SEER MARINE - ABU DHABI
DETAILS : WATER TANK CLEANING & DISINFECTION
DATE OF CLEANING : 09-10 AUGUST 2020
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 09 FEBRUARY 2021

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES