

**KITCHEN EXHAUST SYSTEM
CLEANING
&
DEGREASING

COMPLETION REPORT**



Client: **RAINBOW STEAK HOUSE LLC.**
Contact Person: **Mr. Satheesh P.K.**
QHSE Manager
Site Details: **Rainbow Steak House, Mussaffah.**
Date: **25 October 2018**



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline Environmental
Services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <u>Rainbow Hotel</u>		CONTACT PERSON: <u>Sathish</u>	
SITE DETAILS: <u>Rainbow Hall Shabia</u>		CONTACT NO: <u>055-7169700</u>	
NAME OF KITCHEN/DETAILS: <u>Main Kitchen</u>		LOCATION OF KITCHEN: <u>ground floor</u>	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL			
<u>Total kitchen hood - 3 Roof Top Exhaust fan - 2</u>			
COOKING VOLUME	<input checked="" type="checkbox"/> HIGH	<input type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input checked="" type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <u>03</u>
			HOW MANY PANELS <u>04</u>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<u>CONDITION OF KITCHEN DUCT BEFORE CLEANING</u>		<u>CONDITION OF KITCHEN DUCT AFTER CLEANING</u>	
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
			<input type="checkbox"/> DIRTY
			<input type="checkbox"/> VERY DIRTY
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>	
		<u>09-10-2018</u>	
		<u>09-04-2019</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>			
<u>degreaser chemical USED</u>			
<input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Plastic Roll <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials.			
TEAM <input checked="" type="checkbox"/>		TEAM LEADER <u>Bishal</u>	
<u>COMMENTS & RECOMMENDATIONS:</u> <u>Kitchen cleaned & disinfected</u>			
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.			
Crystalline Representative: <u>Bishal Rai</u>		Signature: <u>Bishal</u>	

Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER






CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW


Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER



Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER




Date of Cleaning: 09-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- RAINBOW HOTEL

BEFORE



AFTER





METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : RAINBOW STEAK HOUSE LLC.
CLIENT ADDRESS : P.O BOX: 46663, ABU DHABI, UAE.
CONTACT PERSON : MR. SATHEESH P.K.
SITE DETAILS : RAINBOW STEAK HOUSE, ABU DHABI, UAE.
DETAILS : KITCHEN EXHAUST SYSTEM CLEANING
DATE OF CLEANING : 09 OCTOBER 2018
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS
DATE OF NEXT CLEANING : 09 APRIL 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Kitchen Duct should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES