

# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR

# serco

Bringing service to life

Client : SERCO MIDDLE EAST.  
Contact Person: Mr. Zidhikkul Akbar  
Accommodation Supervisor.  
Site Details : Serco Staff Accommodation,  
Abu Dhabi, UAE.  
Date : 20 May 2019



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

16067

|   |   |   |   |   |   |
|---|---|---|---|---|---|
| CUSTOMER: SERCO FIM   |   |   | CONTACT PERSON: Ahmed   |   |   |
| SITE DETAILS: SERCO, ACCODATION<br>ABU DHABI  |   |   | CONTACT NO:   |   |   |
| TANK DETAILS: REC W- TANK   |   |   | LOCATION DETAILS: UNDER GROUND                                      |   |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |   |
| <b>TYPE OF TANK</b>   |   |   |   |   |   |
| <input checked="" type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED  |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3  | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF                            | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND                      | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>  |   | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED                                    |
| <input type="checkbox"/> LADDER IN  | <input type="checkbox"/> LADDER OUT                                 | <input type="checkbox"/> LEAKS                                      | <input type="checkbox"/> DRAIN LINE                                 | <input type="checkbox"/> VALVES                                     | <input type="checkbox"/> FLOAT VALVE                                |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES  | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA  |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|   |   | 05-05-2019  |   | 05-11-2019  |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |   |   |
| 1. CARELO BIO & PLUS Quantity 250 M2  |   |   |   |   |   |
| 2. Quantity   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |   |   |
| MENTIONED WATER TANK IS CLEANED & DISINFECTED   |   |   |   |   |   |
| Crystalline Representative: SANKAR  |   |   | Signature:  |   |   |

CLEANER WATER GREENER TOMORROW

ISRAR AHMED  
5-5-19

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES



Date of Cleaning: 05-05-2019

**PHOTOGRAPHS**  
**UNDER GROUND RCC WATER TANK**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17139

|  |   |   |   |   |  |
|--|---|---|---|---|--|
| CUSTOMER: <u>Serco</u>   |   |   | CONTACT PERSON: <u>Mr Isreal</u>              |   |  |
| SITE DETAILS: <u>Al Naumi Building</u><br><u>No: C4-A13</u>  |   |   | CONTACT NO: <u>0569924012</u>                 |   |  |
| TANK DETAILS: <u>Sintex Tank</u>   |   |   | LOCATION DETAILS: <u>Roof Top</u>             |   |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL  |   | <input checked="" type="checkbox"/> RESIDENTIAL |   | <input type="checkbox"/> OTHERS             |  |
| <b>TYPE OF TANK</b>  |   |   |   |   |  |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK               | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL        | <input checked="" type="checkbox"/> PLASTIC                        |
| <input type="checkbox"/> CONCRETE COATED   | <input type="checkbox"/> POLYURETHANE     | <input type="checkbox"/> OTHERS                 |   |   |  |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>                      |   |  |
| M3   | USG                                       | L*B*H   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF    | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |   |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY             | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY              | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                  | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS             | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                   | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND         | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>                                  |   | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO    | <input type="checkbox"/> YES                    | <input checked="" type="checkbox"/> NO        | <input type="checkbox"/> NA                 |  |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>                               |   | <b>LEAKS</b>                                |  |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO    | <input type="checkbox"/> YES                    | <input checked="" type="checkbox"/> NO        | <input type="checkbox"/> YES                | <input checked="" type="checkbox"/> NO                             |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>                         |   | <b>PIPES DISINFECTED</b>                    |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES         | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES                | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>                    |   | <b>NEXT CLEANING DATE</b>                   |  |
|  |   | <u>8/5/2019</u>                                 |   | <u>8/11/2019</u>                            |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |   |   |  |
| 1. <u>Carelo bio-plus</u> Quantity <u>300ml</u>  |   |   |   |   |  |
| 2. _____ Quantity _____  |   |   |   |   |  |
| <input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder |   |   |   |   |  |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials                                    |   |   |   |   |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |   |   |  |
| <u>Mensioned Tank is cleaned and disinfected</u>   |   |   |   |   |  |
| Crystalline Representative: <u>Kennedy Wah</u>   |   |   | Signature: <u>[Signature]</u>                 |   |  |

S/C. Alan Lomillo



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17138

|   |   |   |   |   |   |
|---|---|---|---|---|---|
| CUSTOMER: <u>Serco</u>  |   |   | CONTACT PERSON: <u>Mr Isreal</u>                                    |   |   |
| SITE DETAILS: <u>Al Naumi Building</u><br><u>No: C4 - A13</u>   |   |   | CONTACT NO: <u>0569924012</u>                                       |   |   |
| TANK DETAILS: <u>Sintex Tank</u>  |   |   | LOCATION DETAILS: <u>Roof Top</u>                                   |   |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |   | <input checked="" type="checkbox"/> RESIDENTIAL                     |   | <input type="checkbox"/> OTHERS   |   |
| <b>TYPE OF TANK</b>   |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE   | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL  | <input checked="" type="checkbox"/> PLASTIC                         |
| <input type="checkbox"/> CONCRETE COATED  |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3  | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF  | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY  | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS   | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND   | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>  |   | <input checked="" type="checkbox"/> COVERED   | <input type="checkbox"/> DAMAGED <input type="checkbox"/> NA        |
| <b>LADDER IN</b>  | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                             | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |   |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|   |   | <u>8/5/2019</u>   |   | <u>8/11/2019</u>  |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |   |   |
| 1. <u>Carelo bio-plus</u> Quantity <u>300ml</u>   |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder |   |   |   |   |   |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials                                    |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |   |   |
| <u>Refared Tank is cleaned and disinfected.</u>   |   |   |   |   |   |
| Crystalline Representative: <u>Kennedy Wah</u>  |   |   | Signature: <u>[Signature]</u>                                       |   |   |

S/Co CRM Lomibaw

Date of Cleaning: 08-05-2019

**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK – 01 & 02**

**BEFORE**

**SINTEX WATER TANK - 01**



**SINTEX WATER TANK - 02**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17137

|   |   |   |   |   |   |
|---|---|---|---|---|---|
| CUSTOMER: <u>Serco</u>  |   |   | CONTACT PERSON: <u>Mr Isreal</u>                                    |   |   |
| SITE DETAILS: <u>Al Naumi Building</u><br><u>No: CH-A13</u>   |   |   | CONTACT NO: <u>0569924012</u>                                       |   |   |
| TANK DETAILS: <u>Sintex Tank</u>  |   |   | LOCATION DETAILS: <u>Roof Top</u>                                   |   |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |   | <input checked="" type="checkbox"/> RESIDENTIAL                     |   | <input type="checkbox"/> OTHERS                                     |   |
| <b>TYPE OF TANK</b>   |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE   | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED  |   | <input checked="" type="checkbox"/> POLYURETHANE                    | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3  | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF                            | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>  |   | <input checked="" type="checkbox"/> COVERED                         |   |
| <input type="checkbox"/> DAMAGED  |   | <input type="checkbox"/> NA   |   |   |   |
| <b>LADDER IN</b>  | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES  | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA  |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|   |   | <u>8/5/2019</u>   |   | <u>8/11/2019</u>  |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |   |   |
| 1. <u>Carelo bio-plus</u> Quantity <u>300ml</u>   |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder |   |   |   |   |   |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials                                    |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |   |   |
| <u>Refared Tank is cleaned and disinfected</u>  |   |   |   |   |   |
| Crystalline Representative: <u>Kennedy Wlah</u>   |   |   | Signature: <u>[Signature]</u>                                       |   |   |

S/Co CRISTALINO LIMA



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17135

|   |   |   |   |   |   |
|---|---|---|---|---|---|
| CUSTOMER: <u>SercO</u>  |   |   | CONTACT PERSON: <u>Mr Israel</u>                                    |   |   |
| SITE DETAILS: <u>Al Naumi Building Cat 3</u><br><u>SercO Accommodation</u>  |   |   | CONTACT NO: <u>0569924012</u>                                       |   |   |
| TANK DETAILS: <u>Sintex Tank</u>  |   |   | LOCATION DETAILS: <u>Roof Top</u>                                   |   |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |   | <input checked="" type="checkbox"/> RESIDENTIAL                     |   | <input type="checkbox"/> OTHERS                                     |   |
| <b>TYPE OF TANK</b>   |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE   | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED  |   | <input checked="" type="checkbox"/> POLYURETHANE                    | <input type="checkbox"/> OTHERS                                     |   |   |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>  |   |   |
| M3  | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF                            | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |   |   |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>  |   | <input checked="" type="checkbox"/> COVERED                         |   |
| <input type="checkbox"/> DAMAGED  |   | <input type="checkbox"/> NA   |   |   |   |
| <b>LADDER IN</b>  | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>   | <b>FLOAT VALVE</b>  |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>  |   |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES                             | <input type="checkbox"/> NO   | <input type="checkbox"/> YES  | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA  |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>   |   |
|   |   | <u>8/5/2019</u>   |   | <u>8/11/2019</u>  |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |   |   |
| 1. <u>Carelo bio-plus</u> Quantity <u>300ml</u>   |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |   |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |   |   |
| <u>Tank cleaned and disinfected</u>   |   |   |   |   |   |
| Crystalline Representative: <u>Kennedy Wah</u>  |   |   | Signature: <u>[Signature]</u>                                       |   |   |

[Signature]  
She CAMD Lom MAO

Date of Cleaning: 08-05-2019


**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK – 03 & 04**

**BEFORE**



**SINTEX WATER TANK - 03**



**SINTEX WATER TANK - 04**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES


## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : SERCO MIDDLE EAST.  
CLIENT ADDRESS : SERCO – ADIA HQ, ABU DHABI, UAE.  
CONTACT PERSON : MR. ZIDHIKKUL AKBAR  
SITE DETAILS : SERCO STAFF ACCOMMODATION,  
ABU DHABI, UAE.  
DETAILS : WATER TANK CLEANING  
DATE OF CLEANING : MAY 2019  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : NOVEMBER 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES