

**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**





Completion Report for  
**Water Tank Cleaning & Disinfection**

Date: **28 January 2020**  
Client Name: **Hirmas Real Estate LLC**  
Contact Person: **Bashar Abu Salim**  
Designation: **Head Of QHSES**  
Site Detail: **Hiramas Saadiyat Village, Abu Dhabi**



---

**Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017**  
**E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com**

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 1 Part A		<b>Location:</b> Ground level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
<input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		27 January 2020	
		<b>Next Cleaning Date</b>	
		27 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 1 Part A

Before Photo



After Photo





Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 1 Part B		<b>Location:</b> Ground level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
		<input type="checkbox"/> Others	
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	
		<input checked="" type="checkbox"/> NA	
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		27 January 2020	
		<b>Next Cleaning Date</b>	
		27 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 1 Part B

Before Photo




After Photo




Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 2 Part A		<b>Location:</b> Ground level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
<input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Leaks</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Float Valve</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		27 January 2020	
		<b>Next Cleaning Date</b>	
		27 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 2 Part A

Before Photo



After Photo





Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 2 Part B		<b>Location:</b> Ground level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
<input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Leaks</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Float Valve</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		27 January 2020	
		<b>Next Cleaning Date</b>	
		27 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 2 Part B


Before Photo



After Photo




Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected


<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 3 Part A		<b>Location:</b> Ground level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
		<input type="checkbox"/> Others	
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	
		<input checked="" type="checkbox"/> NA	
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		28 January 2020	
		<b>Next Cleaning Date</b>	
		28 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 3 Part A

Before Photo



After Photo




Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Hirmas Saadiyat Village - Abu Dhabi		<b>Contact Number:</b> 0563893251	
<b>Description:</b> GRP Water Tank 3 Part B		<b>Location:</b> Ground Level	
<b>Type Of Building :</b>		<input type="checkbox"/> Commercial	<input checked="" type="checkbox"/> Residential
<input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		28 January 2020	
		<b>Next Cleaning Date</b>	
		28 July 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 3 Part B

Before Photo



After Photo



Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## WATER TANK CLEANING & DISINFECTION

**CLIENT NAME** : HIRMAS REAL ESTATE LLC  
**CONTACT PERSON** : BASHAR ABU SALIM  
**DESIGNATION** : HEAD OF QHSES  
**SITE DETAILS** : HIRAMAS SAADIYAT VILLAGE, ABU DHABI  
**DETAILS** : WATER TANK CLEANING & DISINFECTION  
**DATE OF CLEANING** : 28 JANUARY 2020  
**FREQUENCY OF CLEANING** : HALF YEARLY  
**DATE OF NEXT CLEANING** : 28 JULY 2020

*The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.*



*Ismar Pinto*

## CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES