

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Water Tank Cleaning & Disinfection

Date: **24 August 2024**
Client Name: **Engie cofely**
Contact Person: **Mr. Tinesh Karthikeyan**
Designation: **Site Engineer**
Site Detail: **KHAZNA - DATA CENTRE FM AUH6
MASDAR CITY**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

| | | | |
|---|---|---|---|
| Customer: Engie cofely | | Contact Person: Mr. Tinesh Karthikeyan | |
| Site: KHAZNA - DATA CENTRE FM AUH6 MASDAR CITY | | Contact Number: -  | |
| Description: DOMESTIC COLD WATER TANK PART 2 | | Location: Ground Floor pump room | |
| Type Of Building : | | <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others | |
| Type Of Tank | | | |
| <input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized | | | |
| <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane | | | |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty | | <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty | |
| <input type="checkbox"/> Biofilm <input type="checkbox"/> mold <input type="checkbox"/> Slime | | <input type="checkbox"/> Biofilm <input type="checkbox"/> mold <input type="checkbox"/> Slime | |
| <input type="checkbox"/> Sediment <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust | | <input type="checkbox"/> Sediment <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust | |
| Size of Tank | | | |
| M3: | | USG: 34,000GL | L*B*H: 4x4x4.5 |
| Quantity Of Water | | Manhole | |
| <input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty | | <input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA | |
| Ladder In | Ladder Out | Leaks | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| Drain Line | Valves | Float Valve | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| Tank Cleaned | Tank Disinfected | Pipes Disinfected | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| Chemicals Used | | | |
| Chemical: Hygienx | | Quantity: 100ml | |
| Chemical: | | Quantity: | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input type="checkbox"/> Foot Bath <input type="checkbox"/> Vacuum Cleaner | <input type="checkbox"/> High/low Pressure Jet <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses | <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Oxygen Meter |
| Current Cleaning Date 24 August 2024 | | Next Cleaning Date 24 February 2025 | |
| Crystalline Representative | | Customer Representative | |
| Francis | | Yassir  | |
|  | |  | |

DOMESTIC COLD WATER TANK PART 2

Before Photo



After Photo



The above mention tank is clean & disinfected

| | | | |
|---|--|--|--|
| Customer: Engie cofely | | Contact Person: Mr. Tinesh Karthikeyan | |
| Site: KHAZNA - DATA CENTRE FM AUH6 MASDAR CITY | | Contact Number: -  | |
| Description: DOMESTIC COLD WATER TANK PART 1 | | Location: Ground Floor pump room | |
| Type Of Building : | | <input checked="" type="checkbox"/> Commercial | <input type="checkbox"/> Residential <input type="checkbox"/> Others |
| Type Of Tank | | | |
| <input type="checkbox"/> Concrete | <input checked="" type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input checked="" type="checkbox"/> Dirty | <input type="checkbox"/> Very Dirty | <input checked="" type="checkbox"/> Clean |
| <input type="checkbox"/> Biofilm | <input type="checkbox"/> mold | <input type="checkbox"/> Slime | <input type="checkbox"/> Dirty |
| <input type="checkbox"/> Sediment | <input type="checkbox"/> Mud & Sand | <input type="checkbox"/> Rust | <input type="checkbox"/> Very Dirty |
| | | <input type="checkbox"/> Biofilm | <input type="checkbox"/> mold |
| | | <input type="checkbox"/> Sediment | <input type="checkbox"/> Mud & Sand |
| | | <input type="checkbox"/> Rust | <input type="checkbox"/> Slime |
| | | <input type="checkbox"/> Rust | <input type="checkbox"/> Rust |
| Size of Tank | | | |
| M3: | | USG: 34,000GL | L*B*H: 4x4x4.5 |
| Quantity Of Water | | Manhole | |
| <input type="checkbox"/> Full | <input checked="" type="checkbox"/> Half | <input type="checkbox"/> Empty | <input type="checkbox"/> Covered |
| | | | <input type="checkbox"/> Damaged |
| | | | <input checked="" type="checkbox"/> NA |
| Ladder In | | Ladder Out | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | | |
| Drain Line | | Valves | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | | |
| Tank Cleaned | | Tank Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | | |
| | | Pipes Disinfected | |
| | | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Hygienx | | Quantity: 100ml | |
| Chemical: | | Quantity: | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersible Pump | <input type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input type="checkbox"/> Foot Bath | <input type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Current Cleaning Date | | Next Cleaning Date | |
| 24 August 2024 | | 24 February 2025 | |
| Crystalline Representative | | Customer Representative | |
| Francis | | Yassir  | |
|  | |  | |

DOMESTIC COLD WATER TANK PART 1

Before Photo



After Photo



The above mention water tank is clean & disinfected



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : ENGIE COFELY

CONTACT PERSON : MR. TINESH KARTHIKEYAN

DESIGNATION : SITE ENGINEER

SITE DETAILS : KHAZNA - DATA CENTRE FM AUH6

MASDAR CITY

DETAILS : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING : 24 AUG 2024

FREQUENCY OF CLEANING : HALF YEARLY

DATE OF NEXT CLEANING : 24 FEBRUARY 2025

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES