

WATER TANK CLEANING  
&  
DISINFECTION  
  
COMPLETION REPORT

FOR



Client : **SOUTHERN FOOD AND CATERING SERVICES.**  
Contact Person: Mr. Uttam  
Purchase Executive  
Site Details : Villa no. 14 Madinat Zayed,  
Abu Dhabi, UAE.  
Date : 27 March 2019



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.  
TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



27/03



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17876

CUSTOMER: <u>SFC</u>			CONTACT PERSON: <u>VINOD</u>			
SITE DETAILS: <u>MADINAZAYED-XILLA-14</u> <u>ABUDHABI</u>			CONTACT NO: <u>056-5801309</u>			
TANK DETAILS: <u>POLYTHENE TANK NO: 1</u>			LOCATION DETAILS: <u>ROOF TOP</u>			
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS						
<b>TYPE OF TANK</b>						
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC	
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>			
M3	<u>300</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>			
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>		
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>		
		<u>25-03-2019</u>		<u>25-09-2019</u>		
<b>CHEMICALS &amp; EQUIPMENTS USED</b>						
1. <u>CARELO CARE &amp; BIO PLUS</u> Quantity <u>50 ML</u>						
2. _____ Quantity _____						
<input type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder						
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials						
<b>COMMENTS &amp; RECOMMENDATIONS:</b> <u>TANK CLEANED &amp; DISINFECTION COMPLETED</u>						
Crystalline Representative: <u>K. ANSARI</u>			Signature: <u>Vinod</u>			



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17877

CUSTOMER: <u>SFC</u>			CONTACT PERSON: <u>VINOD</u>		
SITE DETAILS: <u>MADINA ZAYED-VILLA-14</u> <u>ABUDHABI</u>			CONTACT NO: <u>056-5801309</u>		
TANK DETAILS: <u>POLYTHENE TANK-NO.2</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input checked="" type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	<u>300</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF <input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>25-03-2019</u>		<u>25-09-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELO CARE &amp; BIOPLUS</u> Quantity <u>50 ML</u>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTION COMPLETED.</u>					
Crystalline Representative: <u>K. ANSARI</u>			Signature: <u>Vinod</u>		

Date of Cleaning: 25-03-2019

**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK- 01 & 02**

**BEFORE**



**SINTEX WATER TANK- 01**



**SINTEX WATER TANK- 02**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17878

CUSTOMER: <u>SEC</u>			CONTACT PERSON: <u>VINOD</u>		
SITE DETAILS: <u>MADINA ZAYED-VILLA</u> <u>ABU DHABI - 14</u>			CONTACT NO: <u>056-5201309</u>		
TANK DETAILS: <u>POLYTHENE TANK-3</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL			<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	<u>800</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF
<input type="checkbox"/> EMPTY					
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> DAMAGED	
<input checked="" type="checkbox"/> COVERED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>25-09-2019</u>		<u>25-09-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELO CARE 8 BIO PLUS</u> Quantity <u>50 ML</u>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTION COMPLETED.</u>					
Crystalline Representative: <u>KANSALI</u>			Signature: <u>Vinod</u>		



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17879

CUSTOMER: <u>SFC</u>			CONTACT PERSON: <u>VINOD</u>								
SITE DETAILS: <u>MADINA ZAYED-VILLA</u> <u>ABUDHABI 14</u>			CONTACT NO: <u>056-5801309</u>								
TANK DETAILS: <u>POLYTHENE TANK-4</u>			LOCATION DETAILS: <u>ROOF TOP</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
<b>TYPE OF TANK</b>											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>								
M3	<u>800</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY					
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>								
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA					
<input type="checkbox"/> LADDER IN		<input type="checkbox"/> LADDER OUT		<b>LEAKS</b>		<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>			<b>TANK DISINFECTED</b>			<b>PIPES DISINFECTED</b>					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NA			
<b>LAST CLEANING DATE</b>			<b>CURRENT CLEANING DATE</b>			<b>NEXT CLEANING DATE</b>					
			<u>25-03-2019</u>			<u>25-09-2019</u>					
<b>CHEMICALS &amp; EQUIPMENTS USED</b>											
1. <u>CARELO CARE 8 BIO PLUS</u> Quantity <u>50 ml</u>											
2. _____ Quantity _____											
<input type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
<b>COMMENTS &amp; RECOMMENDATIONS:</b>											
<u>TANK CLEANED &amp; DISINFECTION COMPLETED</u>											
Crystalline Representative: <u>K ANSARI</u>						Signature: <u>Vinod-K</u>					

Date of Cleaning: 25-03-2019

**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK- 03 & 04**

**BEFORE**


**SINTEX WATER TANK- 03**



**SINTEX WATER TANK- 04**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17874

CUSTOMER: <u>SFC @</u>			CONTACT PERSON: <u>VINOD</u>		
SITE DETAILS: <u>MADINA ZAYED - XILLA-14 ABUDHABI</u>			CONTACT NO: <u>0565801309</u>		
TANK DETAILS: <u>RCC WATER TANK NO. 5</u>			LOCATION DETAILS: <u>SOMING POOL AREA</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<b>TYPE OF TANK</b>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	<u>1500</u>	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF <input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>25-03-2019</u>		<u>25-09-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELO CARE J BIO Plus</u> Quantity <u>100 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump	<input type="checkbox"/> High /Low Pressure jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights	<input checked="" type="checkbox"/> Foot Bath	<input type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Mater	<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
<b>COMMENTS &amp; RECOMMENDATIONS:</b> <u>TANK CLEANED &amp; DISINFECTION COMPLETED.</u>					
Crystalline Representative: <u>K. ANSARI</u>			Signature: <u>Vinod</u>		




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 25-03-2019

**PHOTOGRAPHS**  
**SWIMMING POOL AREA RCC WATER TANK**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : SOUTHERN FOOD AND CATERING SERVICES.

CLIENT ADDRESS : P.O. BOX:44145, ABU DHABI, U A E.

CONTACT PERSON : MR. UTTAM.

SITE DETAILS : VILLA #14, MADINAT ZAYED, ABU DHABI.

DETAILS : WATER TANK CLEANING

DATE OF CLEANING : 25 MARCH 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 25 SEPTEMBER 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES