

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Water Tank Cleaning & Disinfection

Date: **10 March 2020**
Client Name: **Hirmas Real Estate LLC**
Contact Person: **Bashar Abu Salim**
Designation: **Head Of QHSES**
Site Detail: **Hiramas Saadiyat Village, Abu Dhabi**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Hirmas Real Estate LLC		Contact Person: Mr. Bashar Abu Salim	
Site: Hirmas Saadiyat Village - Abu Dhabi		Contact Number: 0563893251	
Description: Domestic Water Tank 01		Location: Ground Level	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input checked="" type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3: 6000		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input type="checkbox"/> Half	<input checked="" type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
Ladder In		Ladder Out	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio		Quantity: 20l	
Chemical: Carela bio plus		Quantity: 20l	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		10 March 2020	
		Next Cleaning Date	
		10 March 2021	
Crystalline Representative		Customer Representative	
			

Domestic Water Tank 01

Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : HIRMAS REAL ESTATE LLC

CONTACT PERSON : BASHAR ABU SALIM

DESIGNATION : HEAD OF QHSES

SITE DETAILS : HIRAMAS SAADIYAT VILLAGE, ABU DHABI

DETAILS : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING : 10 MARCH 2020

FREQUENCY OF CLEANING : YEARLY

DATE OF NEXT CLEANING : 10 MARCH 2021

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Ismar Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES