

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**




Completion Report for

Sewage Tank/Lifting Station Cleaning

Date: **03 November 2019**
Client Name: **Tafawuq Facility Management**
Contact Person: **Mr. Sarjun Hussain**
Designation: **CAFM Agent**
Site Detail: **Al Rayyana**



Customer: Tafawuq Facility Management			Contact Person: Mr. Sarjun Hussain		
Site: Al Rayyana Development, Abu Dhabi			Contact Number: 0543061256		
Description: RCC_SEWAGE TANK			Location: TAFAWUQ (BASEMENT)		
Type Of Building:		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential	<input type="checkbox"/> Others	
Type Of Tank					
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized		
<input type="checkbox"/> Steel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Poly Tank		
<input type="checkbox"/> Others					
Size of Tank			Quantity Of Sludge		
M3:	USG:	L*B*H:	<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty
Condition before cleaning			Condition after cleaning		
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust
Waste Liquid Pumped		Sludge Removed		Condition Of Pump	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty
Tank Cleaned			Tank Disinfected		
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No		<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Chemicals Used					
Chemical:			Quantity:		
Chemical:			Quantity:		
Equipments Used					
<input type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights		
<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Meter		
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Air Mask	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Cleaning Materials		
<input type="checkbox"/> Waste Tanker	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Coverall		
Last Cleaning Date		Current Cleaning Date		Next Cleaning Date	
-		02 November 2019		02 May 2020	
Crystalline Representative			Customer Representative		
					

RCC_SEWAGE TANK

Before Photo




After Photo




Before Photo



After Photo



We removed waste, tissues and feces from the above mentioned and cleaned properly

Customer: Tafawuq Facility Management			Contact Person: Mr. Sarjun Hussain		
Site: Al Rayyana Development, Abu Dhabi			Contact Number: 0543061256		
Description: RCC_SEWAGE TANK			Location: TAWAWUQ (BASEMENT)		
Type Of Building:		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential	<input type="checkbox"/> Others	
Type Of Tank					
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized		
<input type="checkbox"/> Steel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Poly Tank		
<input type="checkbox"/> Others					
Size of Tank			Quantity Of Sludge		
M3:	USG:	L*B*H:	<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty
Condition before cleaning			Condition after cleaning		
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust
Waste Liquid Pumped		Sludge Removed		Condition Of Pump	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty
Tank Cleaned			Tank Disinfected		
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No		<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Chemicals Used					
Chemical:			Quantity:		
Chemical:			Quantity:		
Equipments Used					
<input type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights		
<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Meter		
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Air Mask	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Cleaning Materials		
<input type="checkbox"/> Waste Tanker	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Coverall		
Last Cleaning Date		Current Cleaning Date		Next Cleaning Date	
-		02 November 2019		02 May 2020	
Crystalline Representative			Customer Representative		
					

RCC_SEWAGE TANK

Before Photo



After Photo



Before Photo



After Photo



We removed waste, tissues and feces from the above mentioned and cleaned properly

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

GREASE TRAP CLEANING

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT
CONTACT PERSON : MR. SARJUN HUSSAIN
DESIGNATION : CAFM AGENT
SITE DETAILS : AL RAYYANA
DETAILS : SEWAGE TANK/LIFTING STATION CLEANING
DATE OF CLEANING : 02 NOVEMBER 2019
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 02 MAY 2020

The above system is thoroughly cleaned and all the solids and debris removed and disposed.

Regular, preventive maintenance will ensure removal of solids which settle at the bottom, reducing its capacity and efficiency.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES