

SEWAGE SUMP PIT TANK CLEANING

COMPLETION REPORT

For

MULTIPLEX

Client : **Multiplex Services LLC.**
Contact Person: Mr. Azmath Khan
Asst. Facilities Manager
Site Details : Al Wathba New Kitchen,
Abu Dhabi, UAE.
Date : 11 October 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

Crystalline environmental Services

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIRONMENTAL SERVICES

1153

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>Multiplex / Al Wathba</u>	CONTACT PERSON: <u>Mr Manshooor</u>
SITE DETAILS: <u>New Kitchen Al Wathba</u>	CONTACT NUMBER: <u>0551958075</u>
NAME OF MANHOLE: <u>Sump pit</u>	LOCALISQTION: <u>outside</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP
 DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

Sump pit

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD
 BIOFILMS SLIME GREASE ROOT SAND MOULDS
 OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS:

one sump pump working and one not working

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>10/10/2018</u>	<u>10/4/2019</u>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE
 EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT
 LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE
 TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION:

Crystalline representative: <u>Kennedy Wah Bahni</u>	Signature: <u>[Signature]</u>
Customer/Customer representative: <u>0551958075</u>	Signature: <u>[Signature]</u>

Date of Cleaning: 10-10-2018

PHOTOGRAPHS
RCC SUMP PIT CLEANING - NEW KITCHEN AL WATHBA

BEFORE CLEANING



AFTER CLEANING



Date of Cleaning: 10-10-2018

PHOTOGRAPHS
RCC SUMP PIT CLEANING - NEW KITCHEN AL WATHBA

BEFORE CLEANING



AFTER CLEANING



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

SEWAGE SUMP PIT TANKS

CLIENT NAME : MULTIPLEX SERVICES LLC.

CLIENT ADDRESS : P.O. BOX: 113503, ABU DHABI, UAE.

CONTACT PERSON : MR. AZMATH KHAN.

SITE DETAILS : AL WATHBA NEW KITCHEN, ABU DHABI.

DETAILS : SUMP PIT TANK CLEANING

DATE OF CLEANING : 10 OCTOBER 2018

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 10 APRIL 2019

The procedures employed in this cleaning and disinfection comply with HIS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire Sump pit tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES