

**MANHOLE CLEANING  
&  
SERVICING  
COMPLETION REPORT**

**For**



شركة يوش للضيافة  
YOSH HOSPITALITY LLC

Contact Person : Mr. Ashraf Abdelgader  
Facilities Manager  
Site Details : Property No- 1241401,  
Khalifa City Villa - 41, Abu Dhabi.  
Service Date : 25 September 2018  
Next Service Date : 25 March 2019



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

**Crystalline environmental  
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



# CRYSTALLINE ENVIRONMENTAL SERVICES

1023

## MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

|  |                                       |
|--|---------------------------------------|
| CUSTOMER: SINYAR - F/M   | CONTACT PERSON: RAJU KOMAR VJAY KOMAR |
| SITE DETAILS: 124401 - VINA - 41   | CONTACT NUMBER: 056-998-0543          |
| NAME OF MANHOLE:   | LOCALISQTION:                         |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL |                                       |

### PART OF DRAINAGE

MANHOLE  UNDERGROUND DRAINAGE PIPE  GULLY TRAP  GREASE TRAP

DRAINAGE PIPE  APPARENT DRAINAGE PIPE  EMBEDDED DRAINAGE PIPE

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY  DIRTY  VERY DIRTY  RUST  SEDIMENTS  MUD

BIOFILMS  SLIME  GREASE  ROOT  SAND  MOULDS

OBSTRUCT  BLOCK  FLUENT FLOW  LOW FLOW  ANOTHER: \_\_\_\_\_

|   |  |  |  |
|---|--|--|--|
| <b>MANHOLE BLOCKED</b>  | <b>GULLY TRAP BLOCKED</b>                                | <b>DRAINAGE BLOCKED</b>                                  | <b>ALL BLOCKED</b>                                       |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO |

### COMMENTS:

MANHOLE AND GULLY TRAP COVER:  COVERED  DAMAGED  BLOCKED  ADAPTED

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN  CLEAN  VERY CLEAN  FLUENT FLOW  LOW FLOW  UNBLOCK

|                           | MANHOLE | GULLY TRAP | STORM WATER | DRAINAGE | TOTAL |
|---------------------------|---------|------------|-------------|----------|-------|
| NUMBER OF MANHOLE CLEANED | 11      | 09         |             |          |       |
| NUMBER OF MANHOLE BLOCKED |         |            |             |          |       |

### ACCESS

LADDER IN  NO LADDER

|   |   |  |   |
|---|---|--|---|
| <b>MANHOLE CLEANED</b>  | <b>GULLY TRAP CLEANED</b>   | <b>DRAINAGE CLEANED</b>                                  | <b>ALL DISINFECTED</b>  |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

### SERVICES OF DATES

|                           |                           |                           |
|---------------------------|---------------------------|---------------------------|
| <b>LAST CLEANING DATE</b> | <b>LAST CLEANING DATE</b> | <b>LAST CLEANING DATE</b> |
|                           | 25-09-2018                | 25-03-2019                |

### CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE  JETTING MACHINE  MULTIGAS DETECTEUR  INLET WATER HOSE

EXTENTION CORDS  VACCUM CLEANER  VENTILATION FAN  CLEANING MAT

LED LIGHTS  PLASTICS ROLL  PLASTICS BAGS  SUITABLE PPE

TRIPOD  AIR REPAIR 7D-A  DEGREASER CHEMICAL  LADDER

### COMMENTS AND RECOMMENDATION:

|  |                        |
|--|------------------------|
| Crystalline representative: HARI S           | Signature: [Signature] |
| Customer/Customer representative: RAJU KOMAR | Signature: [Signature] |

CLEANER WATER GREENER TOMORROW

RAJU KOMAR

Web: www.crystalline-uae.com  
 E-mail: info@crystalline-uae.com  
 Tel.: +971 55 7167017

Date of Cleaning: 25-09-2018

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 41)**

**BEFORE CLEANING**



**AFTER CLEANING**



**CLEANER WATER GREENER TOMORROW**

Date of Cleaning: 25-09-2018

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 41)**

**BEFORE CLEANING**



**AFTER CLEANING**




**CLEANER WATER GREENER TOMORROW**


Date of Cleaning: 25-09-2018

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 41)**

**BEFORE CLEANING**



**AFTER CLEANING**



Date of Cleaning: 25-09-2018

**CLEANER WATER GREENER TOMORROW**




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 41)**

**BEFORE CLEANING**



**AFTER CLEANING**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

**CLIENT NAME** : YOSH HOSPITALITY LLC.  
**CLIENT ADDRESS** : P.O. BOX: 4347, ABU DHABI, UAE.  
**CONTACT PERSON** : MR. ASHRAF ABDELGADER  
**SITE DETAILS** : PROPERTY NO – 1241401, ABU DHABI, UAE.  
**DETAILS** : MANHOLE & GULLY TRAP CLEANING  
**DATE OF CLEANING** : 25 SEPTEMBER 2018  
**FREQUENCY OF CLEANING** : EVERY SIX (6) MONTHS  
**DATE OF NEXT CLEANING** : 25 MARCH 2019

*The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines*

*The entire Manhole & Gully Trap should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES