


**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Grease Trap Cleaning

Date: **02 January 2021**
Client Name: **Tafawuq Facility Management**
Contact Person: **Mr. Saleem Al Saadi**
Designation: **Facilities Manager**
Site Detail: **Al Wadi Advaenture Water Park -- Al
Ain**



Customer: Tafawuq Facility Management		Contact Person: Mr. Saleem Al Saadi	
Site: Wadi Adventure Water Park - Al Ain		Contact Number: 054 791 3045	
Description: Type C- Trap Cleaning 01		Location: Surf cafe building front.	
Type Of Building <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input checked="" type="checkbox"/> Others			
Type of Grease Trap			
Type A <input type="checkbox"/> Yes <input type="checkbox"/> No	Type B <input type="checkbox"/> Yes <input type="checkbox"/> No	Type C <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Other <input type="checkbox"/> Yes <input type="checkbox"/> No
Condition Of Grease Trap			
<input type="checkbox"/> Little Dirty	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Sludge
<input type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
Condition Of Strainers		Condition Of Baffels	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input type="checkbox"/> Good	<input type="checkbox"/> Faulty
Condition Of Pipes			
Inlet Pipes		Outlet Pipes	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	<input checked="" type="checkbox"/> Good
			<input type="checkbox"/> Leakage
			<input type="checkbox"/> Blockage
Grease Trap Cover			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
Condition Of Grease Trap after cleaning			
Clean		Flow	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Number of Grease Trap Cleaned			
Type A:	Type B:	Type C 01	Other:
			Total: 01
Equipments Used			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input checked="" type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input type="checkbox"/> LED Lights
<input type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
Last Cleaning Date		Current Cleaning Date	Next Cleaning Date
-		02 January 2021	02 July 2021
Crystalline Representative		Customer Representative	
			

Type C- Trap Cleaning 01

Before Photo



After Photo



Before Photo



After Photo



We mention Grease Trap Cleaned

Type C- Trap Cleaning 01

Before Photo



After Photo




Before Photo



After Photo



We mention Grease Trap Cleaned

Customer: Tafawuq Facility Management		Contact Person: Mr. Saleem Al Saadi	
Site: Wadi Adventure Water Park - Al Ain		Contact Number: 054 791 3045	
Description: Type C- Trap Cleaning 02		Location: Surf cafe building front.	
Type Of Building <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input checked="" type="checkbox"/> Others			
Type of Grease Trap			
Type A <input type="checkbox"/> Yes <input type="checkbox"/> No		Type B <input type="checkbox"/> Yes <input type="checkbox"/> No	
Type C <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Other <input type="checkbox"/> Yes <input type="checkbox"/> No	
Condition Of Grease Trap			
<input type="checkbox"/> Little Dirty	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Sludge
<input type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
Condition Of Strainers		Condition Of Baffels	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input type="checkbox"/> Good	<input type="checkbox"/> Faulty
Condition Of Pipes			
Inlet Pipes		Outlet Pipes	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage <input type="checkbox"/> Blockage	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage <input type="checkbox"/> Blockage
Grease Trap Cover			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
Condition Of Grease Trap after cleaning			
Clean		Flow	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Number of Grease Trap Cleaned			
Type A:	Type B:	Type C 01	Other: Total: 01
Equipments Used			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input checked="" type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input type="checkbox"/> LED Lights
<input type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	02 January 2021	02 July 2021	
Crystalline Representative		Customer Representative	
			

Type C- Trap Cleaning 02

Before Photo



After Photo



Before Photo



After Photo



We mention Grease Trap Cleaned

Type C- Trap Cleaning 02

Before Photo



After Photo




Before Photo



After Photo



We mention Grease Trap Cleaned

Customer: Tafawuq Facility Management		Contact Person: Mr. Saleem Al Saadi	
Site: Wadi Adventure Water Park - Al Ain		Contact Number: 054 791 3045	
Description: Type C- Trap Cleaning		Location: Building 05.	
Type Of Building <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input checked="" type="checkbox"/> Others			
Type of Grease Trap			
Type A <input type="checkbox"/> Yes <input type="checkbox"/> No	Type B <input type="checkbox"/> Yes <input type="checkbox"/> No	Type C <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Other <input type="checkbox"/> Yes <input type="checkbox"/> No
Condition Of Grease Trap			
<input type="checkbox"/> Little Dirty	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Sludge
<input type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
Condition Of Strainers		Condition Of Baffels	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input type="checkbox"/> Good	<input type="checkbox"/> Faulty
Condition Of Pipes			
Inlet Pipes		Outlet Pipes	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	<input checked="" type="checkbox"/> Good
			<input type="checkbox"/> Leakage
			<input type="checkbox"/> Blockage
Grease Trap Cover			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
Condition Of Grease Trap after cleaning			
Clean		Flow	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Number of Grease Trap Cleaned			
Type A:	Type B:	Type C 01	Other:
			Total: 01
Equipments Used			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input checked="" type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input type="checkbox"/> LED Lights
<input type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
Last Cleaning Date		Current Cleaning Date	Next Cleaning Date
-		02 January 2021	02 July 2021
Crystalline Representative		Customer Representative	
			

Type C- Trap Cleaning

Before Photo



After Photo



Before Photo



After Photo



We mention Grease Trap Cleaned

Type C- Trap Cleaning

Before Photo



After Photo



Before Photo



After Photo



We mention Grease Trap Cleaned

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

GREASE TRAP CLEANING

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT

CONTACT PERSON : MR. SALEEM AL SAADI

DESIGNATION : FACILITIES MANAGER

SITE DETAILS : AL WADI ADVAENTURE WATER PARK -- AL AIN

DETAILS : GREASE TRAP CLEANING

DATE OF CLEANING : JAN 2021

FREQUENCY OF CLEANING : HALF YEARLY

DATE OF NEXT CLEANING : 02 JUNE 2021

The above system is thoroughly cleaned and all the solids and debris removed and disposed.

Regular, preventive maintenance will ensure system operating at maximum efficiency.



Insmanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES