ENVIRONMENTAL SERVICES FOR A GREENER TOMORROW... ONE STEP AT A TIME.

Completion Report for

Water Tank Cleaning & Disinfection

Date: **29 February 2020**
Client Name: **Sinyar - Presidential Palace**
Contact Person: **Mr. Ankit Rawat**
Designation: **Third Party Services Supervisor**
Site Detail: **PRESIDENTIAL PALACE - ABU DHABI**

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17716

CUSTOMER: SIVYAR	CONTACT PERSON: MR. AUGETH
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE-W.TANK-01	LOCATION DETAILS: LG. 0115

TYPE OF BUILDING: ☑ COMMERCIAL　　☐ RESIDENTIAL　　☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 202488 USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-02-2020	15-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC　　　　Quantity 2000 ML

2. _____　　　　Quantity _____

☑ Submersibel Pump　☑ High/Low Pressure Jet　☑ Extension Cords　☑ LED Lights　☑ Foot Bath　☑ Ladder
☑ Ventilating Fan　☑ Suction/Discharge Hoses　☑ Oxygen Meter　☑ Vacuum Cleaner　☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature:
Customer/Customer representative: ANKIT RAWAT	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17718

CUSTOMER: SINYAR	CONTACT PERSON: MR. ANGIETH
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: IRRIGATION. W. TANK. 01	LOCATION DETAILS: LG-0117

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	2173806 USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

	MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	18-02-2020	18-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 4500 ML

2. ___   Quantity ___

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: ANKIT RAWN	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17717

CUSTOMER: SINYAR	CONTACT PERSON: MR. ANGETH
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE- W.TANK-02	LOCATION DETAILS: LG-0116 A

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[✓] CONCRETE	[ ] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED	[ ] POLYURETHANE	[ ] OTHERS			

SIZE OF TANK / QUANTITY OF WATER

M3	202488 USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED	TANK DISINFECTED	PIPES DISINFECTED
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [ ] NO [✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	19-02-2020	19-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 2000 ML

2. _____   Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit Rawa	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17720

CUSTOMER: SINYAR	CONTACT PERSON: Ankit Ram
SITE DETAILS: Q.A.W.ABUDHABI	CONTACT NO: 0563668847
TANK DETAILS: MAKE UP.W.TANK.01	LOCATION DETAILS: B-10102

TYPE OF BUILDING: [✓] COMMERCIAL   [ ] RESIDENTIAL   [ ] OTHERS

TYPE OF TANK

[✓] CONCRETE	[ ] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 647644 USG		L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES [ ] NO [✓] NA	

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	20-02-2020	20-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 3500ML

2. _____   Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit Ram	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17719

CUSTOMER: SINYAR	CONTACT PERSON: MR. ANGETH
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: IRRIGATION W.TANK 02	LOCATION DETAILS: LG-0117-A
TYPE OF BUILDING: ☑ COMMERCIAL	☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES ☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	22-02-2020	22-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 6000 mL

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HABIS	Signature: HABIS
Customer/Customer representative: ANKIT RAUM	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17722

CUSTOMER: SINYAR	CONTACT PERSON: Ankit Rawat
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: FIRE FIGHTING WTANKO	LOCATION DETAILS: LG. 107
TYPE OF BUILDING: ☑ COMMERCIAL	☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3 249643	USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES ☐ NO ☑ NA	

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	23-02-2020	23-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 1500ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☐ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit Rawat	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17721

CUSTOMER: STNYAR	CONTACT PERSON: ANKIT Pawa
SITE DETAILS: Q.A.W.ABU DHABI	CONTACT NO: 056 4208324
TANK DETAILS: MAKE UP W TANK 02	LOCATION DETAILS: B-10102
TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS	

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 569661 USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	24-02-2020	24-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 3000ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: ANKIT Pawa	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17723

CUSTOMER: SINYAB	**CONTACT PERSON:** ANKIT Paul
SITE DETAILS: Q.A.W. ABUDHABI	**CONTACT NO:** 0564208324
TANK DETAILS: FIRE FIGHTING. W.TANK 02	**LOCATION DETAILS:** LG-108-A

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[✓] CONCRETE	[ ] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK / QUANTITY OF WATER

SIZE OF TANK			QUANTITY OF WATER		
M3 249643 USG		L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / AFTER CLEANING

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA
LADDER IN	**LADDER OUT**	**LEAKS**	**DRAIN LINE**	**VALVES**	**FLOAT VALVE**
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES [ ] NO	[✓] NA	

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	25-02-2020	25-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC _____ Quantity 1500 ML

2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative:	HARIS	Signature: HARIS
Customer/Customer representative:	ANKIT Paul	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17727

CUSTOMER: SIQYAR	CONTACT PERSON:
SITE DETAILS: Q.A.W.ABU DHABI	CONTACT NO:
TANK DETAILS: POTABLE G.R.P. WTANK.	LOCATION DETAILS: PP4. LG.105

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	1540 USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES	[ ] NO [✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26-02-2020	26-05-2020

CHEMICALS & EQUIPMENTS USED

1. ___CRYSTAL SHC___ Quantity ___300ML___

2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [ ] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative:	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17728

CUSTOMER: SINYAR	CONTACT PERSON: Amrit
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE. G.R.P. W. TANK.	LOCATION DETAILS: P.P.3. LG. 0105

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	1540 USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED	TANK DISINFECTED	PIPES DISINFECTED		
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES	[ ] NO	[✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26-02-2020	26-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC _____ Quantity 300 mL

2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Amrit Return	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17726

CUSTOMER: SINYAR	**CONTACT PERSON:** ANKIT
SITE DETAILS: Q.A.H. ABUDHABI	**CONTACT NO:** 056420832 9
TANK DETAILS: POTABL·G·R·P·W·TANK.	**LOCATION DETAILS:** C·P·W· LG-0210
TYPE OF BUILDING: ☑ COMMERCIAL	☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	3170 USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	**LADDER OUT**	**LEAKS**	**DRAIN LINE**	**VALVES**	**FLOAT VALVE**
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED / TANK DISINFECTED / PIPES DISINFECTED

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26-02-2020	26-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 300ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS   **Signature:** HARIS

Customer/Customer representative: ANKIT   **Signature:**

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17725

CUSTOMER: SINYAR	CONTACT PERSON: Ankit Rawa
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE. G.RP. W.TANK.	LOCATION DETAILS: H.H.W. LG-0119

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	4226	USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

			☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	**LADDER OUT**	**LEAKS**	**DRAIN LINE**	**VALVES**	**FLOAT VALVE**
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED / TANK DISINFECTED / PIPES DISINFECTED

☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26-02-2020	26-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 350 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☐ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17724

CUSTOMER: SINYAR	CONTACT PERSON: ANKIT
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE-G.R.P. W. TANK.	LOCATION DETAILS: VP.W-LG-0213

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	3170 USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

			☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED	TANK DISINFECTED	PIPES DISINFECTED
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☐ NO ☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26-02-2020	26-05-2020

CHEMICALS & EQUIPMENTS USED

1. _CRYSTAL SHC_ Quantity _300ML_

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATERTANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit Pawan	Signature:

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17729

CUSTOMER: SINYAR	CONTACT PERSON: ANKIT
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE. G.R.P.W.TANK.	LOCATION DETAILS: P.M.M.B-PART-01-LG-0106

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 748	USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO ☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27-02-2020	27-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 200ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATERTANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17730

CUSTOMER: SINYAB	**CONTACT PERSON:** Ankit
SITE DETAILS: Q.A.W. ABUDHABI	**CONTACT NO:** 0564208324
TANK DETAILS: POTABLE-G.R.P.W.TANK	**LOCATION DETAILS:** PMMB-PART-05 LG-0504
TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS	

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 **3366** USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	**LADDER OUT**	**LEAKS**	**DRAIN LINE**	**VALVES**	**FLOAT VALVE**
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES ☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27-02-2020	27-05-2020

CHEMICALS & EQUIPMENTS USED

1. _____ CRYSTAL SHC _____ Quantity _____ 300 ML _____

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17731

CUSTOMER:	STNYAR	CONTACT PERSON:	ANKIT
SITE DETAILS:	Q.A.W. ABUDHABI	CONTACT NO:	056 4208324
TANK DETAILS:	POTABLE G.R.P. W TANK	LOCATION DETAILS:	P.M.MB. PART-11 LG-1104

TYPE OF BUILDING: ☑ COMMERCIAL   ☐ RESIDENTIAL   ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 2244 USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27-02-2020	27-05-2020

CHEMICALS & EQUIPMENTS USED

1. ___CRYSTAL SHC___ Quantity ___300ML___

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative:	HARIS	Signature:	HARIS
Customer/Customer representative:	ANKIT	Signature:	

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17732

CUSTOMER: SINYAR	CONTACT PERSON: Ankit
SITE DETAILS: Q.A.W - ABUDHABI	CONTACT NO: 056 4208329
TANK DETAILS: POTABLE. G.R.P. W TANK.	LOCATION DETAILS: P.M.MB. PART-14 .LG.1407
TYPE OF BUILDING: ☑ COMMERCIAL	☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK / QUANTITY OF WATER

M3	3366 USG	L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

			☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES ☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27-02-2020	27-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL S17C Quantity 300 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☐ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature HARIS
Customer/Customer representative: Ankit	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17733

CUSTOMER: SINYAR	CONTACT PERSON: Ankit
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 056 4298329
TANK DETAILS: POTABL G.R.P.W.TANK.	LOCATION DETAILS: P.M.MB.PART-15-LG-1503

TYPE OF BUILDING: [✓] COMMERCIAL   [ ] RESIDENTIAL   [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED	[ ] POLYURETHANE	[ ] OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 3927 USG	L*B*H		[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA
LADDER IN	**LADDER OUT**	**LEAKS**	**DRAIN LINE**	**VALVES**	**FLOAT VALVE**
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES	[ ] NO	[✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27-02-2020	27-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 300mL

2. _____   Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Ankit	Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17734

CUSTOMER: STNYAR	CONTACT PERSON: Amar
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 084208329
TANK DETAILS: POTABLE G.R.P.W TANK	LOCATION DETAILS: T.B. CHILLAR ROOM

TYPE OF BUILDING: [✓] COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	[✓] GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	800 USG	L*B*H	☐ FULL	☐ HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	[✓] DIRTY	☐ VERY DIRTY	[✓] CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	[✓] MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES ☐ NO	[✓] YES ☐ NO	☐ YES [✓] NO	[✓] YES ☐ NO	[✓] YES ☐ NO	[✓] YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
[✓] YES	☐ NO	[✓] YES	☐ NO	☐ YES ☐ NO	[✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 200ML

2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder

[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HABIS   Signature: HABIS

Customer/Customer representative: ANKIT   Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17735

CUSTOMER: SINYAR	CONTACT PERSON: ANKIT
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 056 4208324
TANK DETAILS: POTABLE. G.R.P. W. TANK	LOCATION DETAILS: GENARAL STORE-B1-0102

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	6.50 USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

MANHOLE: [ ] COVERED [ ] DAMAGED [ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED	TANK DISINFECTED	PIPES DISINFECTED
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [ ] NO [✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 200 mL

2. _____   Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HABIS   Signature: HABIS

Customer/Customer representative: ANKIT   Signature:

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17736

CUSTOMER: SIXYAB	CONTACT PERSON: Anwar
SITE DETAILS: Q.A.W.ABUDHABI	CONTACT NO: 0864208324
TANK DETAILS: POTABLE.G.R.P.W.TANK	LOCATION DETAILS: MILITARY ACCOMADATION

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 3170 USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☑ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. _CRYSTAL SHC_ Quantity _300 ML_

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative: HARIS	Signature: HARIS
Customer/Customer representative: Anwar	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17737

CUSTOMER: SIXYAB	**CONTACT PERSON:** ANIS
SITE DETAILS: Q.A.H. ABUDHABI	**CONTACT NO:** 0642083???
TANK DETAILS: POTABLE. G.R.P. W TANK	**LOCATION DETAILS:** R.W.A. OFICE

TYPE OF BUILDING: [✓] COMMERCIAL   [ ] RESIDENTIAL   [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	2100	USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

ACCESS	MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED	TANK DISINFECTED	PIPES DISINFECTED
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [ ] NO [✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC   Quantity 300ML

2. ___   Quantity ___

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATERTANK. CLEANED & DISINFECTED

Crystalline representative: HARIS   Signature: HARIS

Customer/Customer representative: ANKIT   Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

Crystalline Environmental Services

WATER TANK - AFTER SERVICE REPORT

17738

CUSTOMER: SINYAR	CONTACT PERSON: Amir
SITE DETAILS: Q.A.W. ABUDHABI	CONTACT NO: 0564208324
TANK DETAILS: POTABLE G.R.P.W.TANK.	LOCATION DETAILS: VISITORS CENTER

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED		[ ] POLYURETHANE	[ ] OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	2100 USG	L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES [ ] NO [✓] NA	

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC Quantity 300mL
2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK. CLEANED & DISINFECTED

Crystalline representative: HARIS Signature: HARIS

Customer/Customer representative: Amir Signature:

CLEANER WATER GREENER TOMORROW

Crystalline Environmental Services

WATER TANK - AFTER SERVICE REPORT

17739

CUSTOMER: SINYAR	**CONTACT PERSON:** AMIR
SITE DETAILS: Q.A.W. ABUDHABI	**CONTACT NO:** 06 4208324
TANK DETAILS: POTABLE · G.R.P.W.TANK	**LOCATION DETAILS:** CEREMONIAL GATE

TYPE OF BUILDING: [✓] COMMERCIAL [ ] RESIDENTIAL [ ] OTHERS

TYPE OF TANK

[ ] CONCRETE	[✓] GRP PANEL	[ ] FRP TANK	[ ] GALVANIZED	[ ] STEEL PANEL	[ ] PLASTIC
[ ] CONCRETE COATED	[ ] POLYURETHANE	[ ] OTHERS			

SIZE OF TANK / QUANTITY OF WATER

SIZE OF TANK			QUANTITY OF WATER		
M3 1100 USG		L*B*H	[ ] FULL	[ ] HALF	[✓] EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / ALFET CLEANING

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
[ ] CLEAN	[✓] DIRTY	[ ] VERY DIRTY	[✓] CLEAN	[ ] DIRTY	[ ] VERY DIRTY
[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME	[ ] BIOFILMS	[ ] MOULDS	[ ] SLIME
[ ] SEDIMENTS	[✓] MUD & SAND	[ ] RUST	[ ] SEDIMENTS	[ ] MUD & SAND	[ ] RUST

ACCESS / MANHOLE

ACCESS		MANHOLE	[ ] COVERED	[ ] DAMAGED	[ ] NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
[✓] YES [ ] NO	[✓] YES [ ] NO	[ ] YES [✓] NO	[✓] YES [ ] NO	[✓] YES [ ] NO	[✓] YES [ ] NO

TANK CLEANED / DISINFECTED / PIPES DISINFECTED

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
[✓] YES	[ ] NO	[✓] YES	[ ] NO	[ ] YES	[ ] NO [✓] NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29-02-2020	29-05-2020

CHEMICALS & EQUIPMENTS USED

1. CRYSTAL SHC Quantity 200ML
2. _____ Quantity _____

[✓] Submersibel Pump [✓] High/Low Pressure Jet [✓] Extension Cords [✓] LED Lights [✓] Foot Bath [✓] Ladder
[✓] Ventilating Fan [✓] Suction/Discharge Hoses [✓] Oxygen Meter [✓] Vacuum Cleaner [✓] Cleaning Materials

COMMENTS AND RECOMMENDATION:

ABOVE MENTIONED WATER TANK CLEANED & DISINFECTED

Crystalline representative:	HARIS	Signature: HARIS
Customer/Customer representative:	AMIR	Signature:

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : SINYAR - PRESIDENTIAL PALACE

CONTACT PERSON : MR. ANKIT RAWAT

DESIGNATION : THIRD PARTY SERVICES SUPERVISOR

SITE DETAILS : PRESIDENTIAL PALACE - ABU DHABI

DETAILS : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING : FEBRUARY 2020

FREQUENCY OF CLEANING : QUARTERLY

DATE OF NEXT CLEANING : 15 MAY 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.

P.O.Box: 131463
CLEANED & DISINFECTED
Abu Dhabi - U.A.E.
CRYSTAL LINE CLEANING & ENVIRONMENTAL SERVICES

CRYSTALLINE CLEANING AND ENVIRNOMENTAL SERVICES