


**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Water Tank Cleaning & Disinfection

Date: **13 November 2019**
Client Name: **Workers Village Real Estate LLC**
Contact Person: **Mr. Bejoy Thomas**
Designation: **Manager- Hygiene**
Site Detail: **Workers Village, Mussafah Abu Dhabi**



Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 01, Part A side	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others	
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full <input type="checkbox"/> Half <input checked="" type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
		Pipes Disinfected	
		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 01 ltr	
Chemical: Carela plus		Quantity: 01 ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
		<input checked="" type="checkbox"/> Extension Cords	
		<input checked="" type="checkbox"/> Ventilating Fan	
		<input checked="" type="checkbox"/> Suction/Discharge Hoses	
		<input checked="" type="checkbox"/> LED Lights	
		<input checked="" type="checkbox"/> Oxygen Meter	
Last Cleaning Date		Current Cleaning Date	
-		13 November 2019	
		Next Cleaning Date	
		13 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning


Before Photo




After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK - KITCHEN 1 (PART A)

DATE OF CLEANING : 13 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 13 MAY 2020

The procedures employed in this cleaning and disinfection comply with HHS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 1, Part B Side	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input checked="" type="checkbox"/> Covered	
<input type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> Empty		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> Yes	
<input type="checkbox"/> No		<input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
		Pipes Disinfected	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 1ltr	
Chemical: Carela plus		Quantity: 1 ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
		<input checked="" type="checkbox"/> Extension Cords	
		<input checked="" type="checkbox"/> Ventilating Fan	
		<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<input checked="" type="checkbox"/> LED Lights		<input checked="" type="checkbox"/> Oxygen Meter	
Last Cleaning Date		Current Cleaning Date	
-		23 November 2019	
		Next Cleaning Date	
		23 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

RCC Water Tank Cleaning

Before Photo



After Photo



Water tank cleaned and disinfected

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK - KITCHEN of (PART B)

DATE OF CLEANING : 23 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS



DATE OF NEXT CLEANING : 23 MAY 2020

The procedures employed in this cleaning and disinfection comply with HIS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 02 part A	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Galvanized	
<input type="checkbox"/> Slime		<input type="checkbox"/> Polyurethane	
<input type="checkbox"/> Rust			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input checked="" type="checkbox"/> Covered	
<input type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> Empty		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> Yes	
<input type="checkbox"/> No		<input checked="" type="checkbox"/> No	
Leaks			
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
<input checked="" type="checkbox"/> No			
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Float Valve			
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No	
<input type="checkbox"/> No			
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Pipes Disinfected			
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
<input checked="" type="checkbox"/> No			
Chemicals Used			
Chemical: Carela bio		Quantity: 01ltr	
Chemical: Carela plus		Quantity: 01ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
		<input checked="" type="checkbox"/> Extension Cords	
		<input checked="" type="checkbox"/> Ventilating Fan	
		<input checked="" type="checkbox"/> Suction/Discharge Hoses	
		<input checked="" type="checkbox"/> LED Lights	
		<input checked="" type="checkbox"/> Oxygen Meter	
Last Cleaning Date		Current Cleaning Date	
-		16 November 2019	
		Next Cleaning Date	
		16 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo




After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK - KITCHEN 02 (PART A)

DATE OF CLEANING : 16 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 16 MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 02 , Part B Side	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Galvanized		<input checked="" type="checkbox"/> Polyurethane	
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input checked="" type="checkbox"/> Covered	
<input type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> Empty		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> Yes	
<input type="checkbox"/> No		<input checked="" type="checkbox"/> No	
Leaks		Drain Line	
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No		<input type="checkbox"/> No	
Valves		Float Valve	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Pipes Disinfected			
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 01 ltr	
Chemical: Carela Plus		Quantity: 01ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
<input checked="" type="checkbox"/> Extension Cords		<input checked="" type="checkbox"/> LED Lights	
<input checked="" type="checkbox"/> Ventilating Fan		<input checked="" type="checkbox"/> Oxygen Meter	
<input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date		Current Cleaning Date	
-		25 November 2019	
		Next Cleaning Date	
		25 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK – KITCHEN 2 (PART B)

DATE OF CLEANING : 25 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 25 MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 3, Part A Side	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input type="checkbox"/> Half	<input checked="" type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	
		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
		Leaks	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Float Valve	
		<input checked="" type="checkbox"/> Yes	
		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 1ltr	
Chemical: Carela Plus		Quantity: 1ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		13 November 2019	
		Next Cleaning Date	
		13 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning


Before Photo



After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK - KITCHEN 3 (PART A)

DATE OF CLEANING : 13 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 13 MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: Kitchen 3, Part B Side	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input checked="" type="checkbox"/> Covered	
<input type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> Empty		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> Yes	
<input type="checkbox"/> No		<input checked="" type="checkbox"/> No	
Leaks		<input type="checkbox"/> Yes	
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
<input checked="" type="checkbox"/> No			
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Float Valve		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> Yes		<input type="checkbox"/> No	
<input checked="" type="checkbox"/> No			
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Pipes Disinfected		<input type="checkbox"/> Yes	
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
<input checked="" type="checkbox"/> No			
Chemicals Used			
Chemical: Carela bio		Quantity: 1ltr	
Chemical: Carela plus		Quantity: 1 ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
<input checked="" type="checkbox"/> Extension Cords		<input checked="" type="checkbox"/> LED Lights	
<input checked="" type="checkbox"/> Ventilating Fan		<input checked="" type="checkbox"/> Oxygen Meter	
<input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date		Current Cleaning Date	
-		27 November 2019	
		Next Cleaning Date	
		27 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

RCC Water Tank Cleaning

Before Photo



After Photo



Water tank cleaned and disinfected

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK - KITCHEN 03 (PART B)

DATE OF CLEANING : 27 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS



DATE OF NEXT CLEANING : 27 MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: O. D 1 part A	
Type Of Building :			
<input type="checkbox"/> Commercial		<input checked="" type="checkbox"/> Residential	
<input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> FRP Tank	
<input type="checkbox"/> Others		<input type="checkbox"/> Concrete Coated	
<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input checked="" type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input checked="" type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input checked="" type="checkbox"/> Covered	
<input type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> Empty		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> Yes	
<input type="checkbox"/> No		<input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
		Pipes Disinfected	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 1ltr	
Chemical: Carela plus		Quantity: 1 ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
		<input checked="" type="checkbox"/> Extension Cords	
		<input checked="" type="checkbox"/> Ventilating Fan	
		<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<input checked="" type="checkbox"/> LED Lights		<input checked="" type="checkbox"/> Oxygen Meter	
Last Cleaning Date		Current Cleaning Date	
-		20 November 2019	
		Next Cleaning Date	
		20 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Above mentioned water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK -- OLD DINING 1(PART A)

DATE OF CLEANING : 20 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 20 MAY 2020

The procedures employed in this cleaning and disinfection comply with HIS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Workers Village Real Estate LLC		Contact Person: Bashar Abu Salim	
Site: Workers Village, Musaffah, Abu Dhabi		Contact Number: 050 714 8606	
Description: RCC Water Tank Cleaning		Location: O. D 1, Part B Side	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	
		<input type="checkbox"/> Moulds	
		<input type="checkbox"/> Slime	
		<input type="checkbox"/> Sediments	
		<input type="checkbox"/> Mud & Sand	
		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input type="checkbox"/> Half	<input checked="" type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
		Leaks	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Float Valve	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio		Quantity: 1ltr	
Chemical: Carela plus		Quantity: 1 ltr	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		30 November 2019	
		Next Cleaning Date	
		30 May 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Water tank has been cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : WORKERS VILLAGE REAL ESTATE LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABUSALIM.

SITE DETAILS : WORKERS VILLAGE, MUSSAFFAH.

DETAILS : RCC WATER TANK – OLD DINING 1 (PART B)

DATE OF CLEANING : 30 NOVEMBER 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 30 MAY 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS

method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES