

WATER TANK CLEANING & DISINFECTION COMPLETION REPORT

FOR



Client : Al Mariah Catering & Camp
Services.
Contact Person: Mr. Anzil Salim
Hygiene Officer.
Site Details : Ruwais Camp T 275,
Abu Dhabi, UAE.
Date : 30 March 2017



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.
TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13028

CUSTOMER: <u>AL MARIAH LLC</u>			CONTACT PERSON: <u>Mr. Anzel Salim</u>								
SITE DETAILS: <u>CAMP - RUWADIS</u>			CONTACT NO: <u>0558780508</u>								
TANK DETAILS: <u>G.R.P. WATER TANK - 01</u>			LOCATION DETAILS: <u>GROUND</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
<u>TYPE OF TANK</u>											
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS							
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>								
M3	<u>48000</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY					
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
<u>ACCESS</u>		<u>MANHOLE</u>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
<u>LADDER IN</u>		<u>LADDER OUT</u>		<u>LEAKS</u>		<u>DRAIN LINE</u>		<u>VALVES</u>		<u>FLOAT VALVE</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<u>TANK CLEANED</u>			<u>TANK DISINFECTED</u>			<u>PIPES DISINFECTED</u>					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> NA		
<u>LAST CLEANING DATE</u>			<u>CURRENT CLEANING DATE</u>			<u>NEXT CLEANING DATE</u>					
			<u>19.03.2018</u>			<u>19.03.2019</u>					
<u>CHEMICALS & EQUIPMENTS USED</u>											
1. <u>CRYSTAL SHC</u> Quantity <u>500ml</u>											
2. <u>CARELO BIO PLUS</u> Quantity _____											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
<u>COMMENTS & RECOMMENDATIONS:</u>											
<u>MENTIONED WATER TANK CLEANED & DISINFECTED</u>											
Crystalline Representative: <u>HARIS</u>						Signature: <u>HARIS</u>					

Anzel
27/03/18

Haris
27/03/18

Date of Cleaning, 19-03-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13029

CUSTOMER: <u>AL MARIAH LLC</u>			CONTACT PERSON: <u>Mrs. Hazel Salim.</u>								
SITE DETAILS: <u>CAMP. RUWADIS</u>			CONTACT NO: <u>0558780508</u>								
TANK DETAILS: <u>SINTEX WATER TANK-02</u>			LOCATION DETAILS: <u>GROUND</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
TYPE OF TANK											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
SIZE OF TANK			QUANTITY OF WATER								
M3	<u>6000</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY					
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED			TANK DISINFECTED			PIPES DISINFECTED					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NA			
LAST CLEANING DATE			CURRENT CLEANING DATE			NEXT CLEANING DATE					
			<u>19.03.2018</u>			<u>19.03.2019</u>					
CHEMICALS & EQUIPMENTS USED											
1. <u>CRYSTAL SHC</u> Quantity <u>500ml</u>											
2. <u>CARELO BIO & PUG</u> Quantity _____											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
COMMENTS & RECOMMENDATIONS:											
<u>MENTINED WATER TANK CLEANED & DISINFECTED</u>											
Crystalline Representative: <u>HARIS</u>						Signature: <u>HARIS</u>					


[Handwritten signature]
19/03/19

[Handwritten signature]
23/3/18



Date of Cleaning: 19-03-2018

PHOTOGRAPHS
GROUND LEVEL SINTEX WATER TANK - 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13030

CUSTOMER: AL MARIAH F/M			CONTACT PERSON: Mr. Anasif Salim								
SITE DETAILS: CAMP - RUWADIS			CONTACT NO: 055878 0508								
TANK DETAILS: SINTEX WATER TANK. 03			LOCATION DETAILS: GROUND								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
<u>TYPE OF TANK</u>											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>								
M3	6000	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY					
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
<u>ACCESS</u>		<u>MANHOLE</u>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
<u>LADDER IN</u>		<u>LADDER OUT</u>		<u>LEAKS</u>		<u>DRAIN LINE</u>		<u>VALVES</u>		<u>FLOAT VALVE</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<u>TANK CLEANED</u>				<u>TANK DISINFECTED</u>				<u>PIPES DISINFECTED</u>			
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA			
<u>LAST CLEANING DATE</u>				<u>CURRENT CLEANING DATE</u>				<u>NEXT CLEANING DATE</u>			
				19.03.2018				19.03.2019			
<u>CHEMICALS & EQUIPMENTS USED</u>											
1. CRYSTALSAC Quantity 500ML											
2. CARELO BIO PLUS Quantity											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
<u>COMMENTS & RECOMMENDATIONS:</u>											
MENTINED WATER TANK CLEANED & DISINFECTED											
Crystalline Representative: HARI S						Signature: HARI S					

[Handwritten signature]
19/03/18

[Handwritten signature]
19/03/18




CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning, 19-03-2018

PHOTOGRAPHS
GROUND LEVEL SINTEX WATER TANK - 03

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT



13031

CUSTOMER: <u>ALMARPAH</u>			CONTACT PERSON: <u>Mr. Anzil belim</u>								
SITE DETAILS: <u>CAMP - RUWDIS</u>			CONTACT NO: <u>0558780508</u>								
TANK DETAILS: <u>SINTEX WATER TANK 04</u>			LOCATION DETAILS: <u>GROUND</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
TYPE OF TANK											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
SIZE OF TANK			QUANTITY OF WATER								
M3	<u>6000</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY					
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED			TANK DISINFECTED			PIPES DISINFECTED					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input type="checkbox"/> NA		
LAST CLEANING DATE			CURRENT CLEANING DATE			NEXT CLEANING DATE					
			<u>20-03-2018</u>			<u>20-03-2019</u>					
CHEMICALS & EQUIPMENTS USED											
1. <u>CRYSTAL SHC</u> Quantity <u>500ML</u>											
2. <u>CARELO Bio & pipes</u> Quantity _____											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials											
COMMENTS & RECOMMENDATIONS:											
<u>MENTINED WATER TANK CLEANED & DISINFECTED</u>											
Crystalline Representative: <u>HARIS</u>						Signature: <u>[Signature]</u>					



Date of Cleaning: 20-03-2018

PHOTOGRAPHS
GROUND LEVEL SINTEX WATER TANK - 04

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13032

CUSTOMER: <u>AL MARIAH</u>			CONTACT PERSON: <u>Mr. Anzil Salim</u>								
SITE DETAILS: <u>CAMP RUWADIS</u>			CONTACT NO: <u>0558780508</u>								
TANK DETAILS: <u>SINTEX WATER TANK 05</u>			LOCATION DETAILS: <u>GROUND</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
TYPE OF TANK											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
SIZE OF TANK			QUANTITY OF WATER								
M3	<u>2000</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY					
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED			TANK DISINFECTED			PIPES DISINFECTED					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NA			
LAST CLEANING DATE			CURRENT CLEANING DATE			NEXT CLEANING DATE					
			<u>20-03-2018</u>			<u>20-03-2019</u>					
CHEMICALS & EQUIPMENTS USED											
1. <u>CRYSTAL SNC</u> Quantity <u>500ML</u>											
2. <u>CARLO BIO & PLUS</u> Quantity _____											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
COMMENTS & RECOMMENDATIONS:											
<u>MENTINED WATER TANK CLEANED & DISINFECTED</u>											
Crystalline Representative: <u>HARIS</u>						Signature: <u>HARIS</u>					

[Handwritten signature]
2018/3/18

[Handwritten signature]
2018/3/18



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning, 20-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK - 05

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13033


CUSTOMER: <u>ALMARIAH</u>			CONTACT PERSON: <u>Mr. Anzil Salim</u>								
SITE DETAILS: <u>CAMP. RCUWDIS</u>			CONTACT NO: <u>0558780508</u>								
TANK DETAILS: <u>SINTEX WATER TANK-06</u>			LOCATION DETAILS: <u>GROUND</u>								
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS							
TYPE OF TANK											
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC						
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS								
SIZE OF TANK			QUANTITY OF WATER								
M3	<u>1500</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY					
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING								
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY						
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME						
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST						
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED			TANK DISINFECTED			PIPES DISINFECTED					
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> NA			
LAST CLEANING DATE			CURRENT CLEANING DATE			NEXT CLEANING DATE					
			<u>20.03.2018</u>			<u>20.03.2019</u>					
CHEMICALS & EQUIPMENTS USED											
1. <u>CRYSTAL SHC</u> Quantity <u>500 ML</u>											
2. <u>CARBO BIO & PLY</u> Quantity _____											
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder											
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials											
COMMENTS & RECOMMENDATIONS:											
<u>MENTINED WATER TANK CLEANED & DISINFECTED</u>											
Crystalline Representative: <u>HARIS</u>						Signature: <u>[Signature]</u>					

[Handwritten signatures and dates]

Date of Cleaning, 20-03-2018

PHOTOGRAPHS
GROUND LEVEL SINTEX WATER TANK - 06

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL MARIAH CATERING & CAMP SERVICES.
CLIENT ADDRESS : P.O.BOX: 206, MUSSAFFAH, ABU DHABI, UAE
CONTACT PERSON : MR. ANZIL SALIM.
SITE DETAILS : RUWAIS CAMP, T 275, ABU DHABI, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : 19 – 20 MARCH 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : 19 SEPTEMBER 2018

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES