

WATER TANK CLEANING & DISINFECTION COMPLETION REPORT

FOR



Client : **Descon Engineering.**
Contact Person: Mr. Daljeet Singh
Camp Administrator
Site Details : Bin Mansour Camp, Al Asab,
Abu Dhabi, UAE.
Date : 13 March 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12901

CUSTOMER: <i>Descon</i>			CONTACT PERSON: <i>Mr. Daljeel</i>		
SITE DETAILS: <i>Bin Mansour, Asab</i>			CONTACT NO: <i>0543058097</i>		
TANK DETAILS: <i>Sinlex 19 tank - 01</i>			LOCATION DETAILS: <i>ground floor</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA		<input type="checkbox"/> NA		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NA		<input type="checkbox"/> NA		<input type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>04/03/2018</i>		<i>04/09/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Septo bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansur</i>			Signature: <i>[Signature]</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12902

CUSTOMER: <u>Duron</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mawow, Asab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinter-w. tank -02</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Curelo bio and ply</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Manoj</u>			Signature: <u>[Signature]</u>		




CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning, 04-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (01 & 02)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12903

CUSTOMER: <u>Deston</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mansour, Bab</u>			CONTACT NO: <u>0542058097</u>		
TANK DETAILS: <u>Sintex. W. tank - 03</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA			<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo bio and plus</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative:			Signature:		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12904

CUSTOMER: <u>Denson</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bismansour, Abab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sintex W. tank - 04</u>			LOCATION DETAILS: <u>Grand floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA			<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carels bio and plus</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mawj</u>			Signature: <u>M. Daljeet</u>		





Date of Cleaning, 04-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (03 & 04)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12905

CUSTOMER: <u>Descor</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mansour, Abab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinlex 20-tank-05</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carolo bio and plus</u> Quantity <u>2some</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mansaj</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


12906

CUSTOMER: <u>Desron</u>			CONTACT PERSON: <u>Mr Daljial</u>		
SITE DETAILS: <u>Bin Mansour, Asab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinterex. W. tank - 06</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo bio and plus</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Marij</u>			Signature: <u>[Signature]</u>		

Date of Cleaning, 04-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (05 & 06)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12907

CUSTOMER: <u>Descon</u>		CONTACT PERSON: <u>Mr. Daljeet</u>	
SITE DETAILS: <u>Bin Mansour, Abab</u>		CONTACT NO: <u>0543058097</u>	
TANK DETAILS: <u>Sinterix 10. tank. -07</u>		LOCATION DETAILS: <u>Ground floor</u>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL	
		<input type="checkbox"/> OTHERS	
TYPE OF TANK			
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED
<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC	<input type="checkbox"/> CONCRETE COATED	<input checked="" type="checkbox"/> POLYURETHANE
		<input type="checkbox"/> OTHERS	
SIZE OF TANK		QUANTITY OF WATER	
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL
		<input checked="" type="checkbox"/> HALF	
		<input type="checkbox"/> EMPTY	
CONDITION OF WATER TANK BEFORE CLEANING		CONDITION OF WATER TANK AFTER CLEANING	
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> DIRTY
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> VERY DIRTY
		<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS
		<input type="checkbox"/> SLIME	<input type="checkbox"/> SLIME
		<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND
		<input type="checkbox"/> RUST	<input type="checkbox"/> RUST
ACCESS		MANHOLE	
		<input checked="" type="checkbox"/> COVERED	
		<input type="checkbox"/> DAMAGED	
		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
LEAKS		DRAIN LINE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
		<input type="checkbox"/> NA	
PIPES DISINFECTED			
<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
		<input type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE	
		<u>04/03/2018</u>	
NEXT CLEANING DATE			
		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED			
1. <u>Carebio bio and plus</u> Quantity <u>250ml</u>			
2. _____ Quantity _____			
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder			
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials			
COMMENTS & RECOMMENDATIONS:			
<u>Mentioned water tank is cleaned and disinfected</u>			
Crystalline Representative: <u>Mansaj</u>		Signature: <u>[Signature]</u>	



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12908

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mansour, Alab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinter. W. tank - 08</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/03/2018</u>		<u>04/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carelo Bio and plus</u> Quantity <u>2 some</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mawj</u>			Signature: <u>[Signature]</u>		





CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 04-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (07 & 08)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12909

CUSTOMER: <u>Descon</u>	CONTACT PERSON: <u>Mr. Daljeet</u>
SITE DETAILS: <u>Bin Mansour, Abu</u>	CONTACT NO: <u>0543-58097</u>
TANK DETAILS: <u>Sintex. W. tank-09</u>	LOCATION DETAILS: <u>Ground floor</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS	

TYPE OF TANK

<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			

SIZE OF TANK

QUANTITY OF WATER

M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
----	-----	-------	-------------------------------	--	--------------------------------

CONDITION OF WATER TANK BEFORE CLEANING

CONDITION OF WATER TANK AFTER CLEANING

<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST

ACCESS

MANHOLE

<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
---	----------------------------------	-----------------------------

LADDER IN

LADDER OUT

LEAKS

DRAIN LINE

VALVES

FLOAT VALVE

<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO			
---	---	---	---	---	--

TANK CLEANED

TANK DISINFECTED

PIPES DISINFECTED

<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
---	---	---

LAST CLEANING DATE

CURRENT CLEANING DATE

NEXT CLEANING DATE

	<u>05/03/2018</u>	<u>05/09/2018</u>
--	-------------------	-------------------

CHEMICALS & EQUIPMENTS USED

- Carelo bio and plus Quantity 250ml
- Quantity _____

<input checked="" type="checkbox"/> Submersible Pump	<input checked="" type="checkbox"/> High/Low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED lights	<input type="checkbox"/> Foot Bath	<input type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input type="checkbox"/> Suction/Discharge Hoses	<input type="checkbox"/> Oxygen Meter	<input type="checkbox"/> Vacuum Cleaner	<input type="checkbox"/> Cleaning Materials	

COMMENTS & RECOMMENDATIONS:

Mentioned water tank is cleaned and disinfected

Crystalline Representative: Manoj

Signature: [Signature]



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12910

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr. Daljeel</u>		
SITE DETAILS: <u>Bin Mansour, Abab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinterex. 6. tank-10</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> DAMAGED	
<input type="checkbox"/> COVERED		<input checked="" type="checkbox"/> COVERED		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carels bio and play</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected.</u>					
Crystalline Representative:			Signature:		




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning, 05-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (09 & 10)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12911

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bior Mansour Mab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinter w. tank-11</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> NA	
<input checked="" type="checkbox"/> COVERED		<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carolo bio and plus</u> Quantity <u>200ml</u>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mamaj</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12912

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mansour, Mab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sintex w. tank-12</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<u>TYPE OF TANK</u>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<u>LADDER IN</u>		<u>LADDER OUT</u>		<u>LEAKS</u>	
<u>DRAIN LINE</u>		<u>VALVES</u>		<u>FLOAT VALVE</u>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>					
1. <u>Carelo bio and plus</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<u>COMMENTS & RECOMMENDATIONS:</u>					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mandi</u>			Signature: <u>[Signature]</u>		




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning, 05-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (11 & 12)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12913

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bin Mansour, Abab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sister W. tank - 13</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carols Bio and plus</u> Quantity <u>200ml</u>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersible Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mawji</u>			Signature: <u>Mawji</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12914

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mrs Daljeet</u>		
SITE DETAILS: <u>Bin Mousour Mab</u>			CONTACT NO: <u>0543058092</u>		
TANK DETAILS: <u>Sintex. w. tank -14</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
<input type="checkbox"/> M3	<input type="checkbox"/> USG	<input type="checkbox"/> L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carels bio and plus</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mansur</u>			Signature: <u>[Signature]</u>		

[Signature]
06/03/18




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 05-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (13 & 14)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12915

CUSTOMER: <u>Descon</u>			CONTACT PERSON: <u>Mr Daljeel</u>		
SITE DETAILS: <u>Bin Mansour Mab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinter x. w. tank -15</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/03/2018</u>		<u>05/09/2018</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo bio and ply</u> Quantity <u>200ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mansur</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12916

CUSTOMER: <u>Descon</u>		CONTACT PERSON: <u>Mr. Daljeet</u>	
SITE DETAILS: <u>Bin Mankour, Abu</u>		CONTACT NO: <u>0543058097</u>	
TANK DETAILS: <u>Sinter. W. tank -16</u>		LOCATION DETAILS: <u>ground floor</u>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL	
		<input type="checkbox"/> OTHERS	
<u>TYPE OF TANK</u>			
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED
<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC	<input type="checkbox"/> CONCRETE COATED	<input checked="" type="checkbox"/> POLYURETHANE
		<input type="checkbox"/> OTHERS	
<u>SIZE OF TANK</u>		<u>QUANTITY OF WATER</u>	
M3	USG	L*B*H	<input type="checkbox"/> FULL
			<input checked="" type="checkbox"/> HALF
			<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>		<u>CONDITION OF WATER TANK AFTER CLEANING</u>	
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN
<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY
<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS
<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS
<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS
<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND
<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>	
<input type="checkbox"/> COVERED		<input type="checkbox"/> DAMAGED	
<input type="checkbox"/> NA			
<u>LADDER IN</u>		<u>LADDER OUT</u>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<u>LEAKS</u>		<u>DRAIN LINE</u>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<u>VALVES</u>		<u>FLOAT VALVE</u>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<u>PIPES DISINFECTED</u>			
<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA			
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>	
		<u>05/09/2018</u>	
<u>NEXT CLEANING DATE</u>			
		<u>05/09/2018</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>			
1. <u>Carlo bio and plus</u> Quantity <u>200ml</u>			
2. _____ Quantity _____			
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder			
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials			
<u>COMMENTS & RECOMMENDATIONS:</u>			
<u>Mentioned water tank is cleaned and disinfected</u>			
Crystalline Representative: <u>Mauj</u>		Signature: <u>[Signature]</u>	

[Signature]
05/03/18



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 05-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (15 & 16)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12917

CUSTOMER: <u>Nelson</u>	CONTACT PERSON: <u>Mr. Duljet</u>
SITE DETAILS: <u>Bin Mansour, Mab</u>	CONTACT NO: <u>0543058097</u>
TANK DETAILS: <u>Sinter w. tank-17</u>	LOCATION DETAILS: <u>Ground floor</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS	

TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST

ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA	
<input type="checkbox"/> LADDER IN	<input checked="" type="checkbox"/> LADDER OUT	<input type="checkbox"/> LEAKS		<input type="checkbox"/> DRAIN LINE	<input checked="" type="checkbox"/> VALVES	<input type="checkbox"/> FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>08/03/2018</u>	<u>08/09/2018</u>

CHEMICALS & EQUIPMENTS USED

- Carelo bio and plus Quantity 250ml
- _____ Quantity _____

Submersibel Pump High/Low Pressure Jet Extension Cords LED lights Foot Bath Ladder
 Ventilating Fan Suction/Discharge Hoses Oxygen Meter Vacuum Cleaner Cleaning Materials

COMMENTS & RECOMMENDATIONS:
Mentioned water tank is cleaned and disinfected

Crystalline Representative: <u>Mawj</u>	Signature: <u>[Signature]</u>
---	-------------------------------



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

12919

CUSTOMER: <u>Descor</u>			CONTACT PERSON: <u>Mr. Daljeet</u>		
SITE DETAILS: <u>Bio Mansour Hab</u>			CONTACT NO: <u>0543058097</u>		
TANK DETAILS: <u>Sinterex. W. tank -18</u>			LOCATION DETAILS: <u>Ground floor</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
				<input type="checkbox"/> DAMAGED	
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
				DRAIN LINE	
				VALVES	
				FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>06/03/2013</u>		<u>06/09/2013</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carels bio and ply</u> Quantity <u>250ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>Mentioned water tank is cleaned and disinfected</u>					
Crystalline Representative: <u>Mansi</u>			Signature: <u>[Signature]</u>		





CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning, 06-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (17 & 18)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


12921

CUSTOMER: <i>Decon</i>			CONTACT PERSON: <i>Mr. Daljeet</i>		
SITE DETAILS: <i>Bir Mansour, Hab</i>			CONTACT NO: <i>0543058097</i>		
TANK DETAILS: <i>Sintex w. tank -19</i>			LOCATION DETAILS: <i>Ground floor</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> NA	
<input type="checkbox"/> COVERED		<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>06/03/2018</i>		<i>06/09/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Care to bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Manoj</i>			Signature: <i>[Signature]</i>		

Date of Cleaning, 06-03-2018

PHOTOGRAPHS
GROUND LEVEL FRP WATER TANK (19)

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : DESCON ENGINEERING.
CLIENT ADDRESS : P.O. BOX: 46821, MBZ CITY, ABU DHABI, UAE.
CONTACT PERSON : MR. DALJEET SINGH.
SITE DETAILS : BIN MANSOUR CAMP, AL ASAB, ABU DHABI.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : MARCH 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : SEPTEMBER 2018

The procedures employed in this cleaning and disinfection comply with HIS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.

Tasmanpinto



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES