

**KITCHEN DUCT CLEANING  
&  
DEGREASING  
COMPLETION REPORT**

**For**

**EMIRATES PARK ZOO** **EMIRATES PARK RESORT**  
حديقة الإمارات للحيوانات منتجع حديقة الإمارات

Client : Emirates Park Zoo.  
Contact Person: Mr. Malik  
Purchasing Department  
Site Details : Qasr Al Turath Restaurant,  
Emirates Park Zoo, Old Shahama,  
Abu Dhabi, UAE.  
Date : 26 May 2019

**Crystalline environmental  
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES



# CRYSTALLINE ENVIROMENTAL SERVICES

## KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1310

CUSTOMER: EMIRATES PARK ZOO	CONTACT PERSON: MY. CHANDRAN
SITE DETAILS: QASR AL YURAYH RESTAURANT	CONTACT NUMBER: 055 524 8145
NAME OF KITCHEN: MAIN KITCHEN	LOCATION: SHARJHA
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input type="checkbox"/> RESIDENCIAL <input checked="" type="checkbox"/> RESTAURANT	

### Type & Size of Hood:

Cooking Volume:	<input type="checkbox"/> Very High	<input checked="" type="checkbox"/> High	<input type="checkbox"/> Medium	<input type="checkbox"/> Low
Type of Filters:	<input type="checkbox"/> Mesh	<input type="checkbox"/> Baffle	<input type="checkbox"/> N/A	
Filters in Place:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	
Filter Cleaning Freq.	<input type="checkbox"/> Daily	<input type="checkbox"/> Weekly	<input type="checkbox"/> Monthly	<input type="checkbox"/> Not Known

### Comments:

### FIRE PROTECTION SYSTEM

Kitchen:	<input type="checkbox"/> Powder	<input type="checkbox"/> CO2	<input type="checkbox"/> Foam	<input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Dry Powder	<input type="checkbox"/> Other
Fire Dampers:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Fusible Links:	<input type="checkbox"/> Yes <input type="checkbox"/> No

### DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel	<input checked="" type="checkbox"/> Stainless Steel	<input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
Access with Tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access	<input type="checkbox"/> Safety Harness	<input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No if No, give details	

### Comments

Doors/Plates Present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels

### Where Installed:

Duct Size & Approx. Length:	Insulated:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Condition of Ducts:	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans:	<input checked="" type="checkbox"/> Upblast	<input type="checkbox"/> Inline	<input type="checkbox"/> Utility <input type="checkbox"/> Others

### Location:

### Condition of Roof:

LAST CLEANING DATE

CURRENT CLEANING DATE

NEXT CLEANING DATE

21-05-2019 22-05-2019 22-11-2019

### CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> JETTING MACHINE	<input checked="" type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input checked="" type="checkbox"/> VACCUM CLEANER
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input checked="" type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input type="checkbox"/> LADDER			

### COMMENTS AND RECOMMENDATION:

KITCHEN HOOD AND EXHAUST SYSTEM CLEANED (COMPLETED)

Crystalline Representative: HARI S  
Signature: [Signature]

Customer Representative: Saif Saad  
Signature: [Signature]



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 21-05-2019


## PHOTOGRAPHS

### KITCHEN HOOD 1 CLEANING- EMIRATES PARK ZOO

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 21-05-2019

**PHOTOGRAPHS**  
**KITCHEN HOOD 2 CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 21-05-2019

**PHOTOGRAPHS**  
**KITCHEN HOOD 3 CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 21-05-2019

**PHOTOGRAPHS**  
**KITCHEN EXHAUST SYSTEM CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**METHODOLOGY:**

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES PARK ZOO.  
CLIENT ADDRESS : P.O. BOX: 111026, ABU DHABI, UAE.  
CONTACT PERSON : MR. MALIK.  
SITE DETAILS : QASR AL TURATH RESTAURANT,  
OLD SHAHAMA, AL BAHIYA STREET,  
ABU DHABI, UAE.  
DETAILS : KITCHEN HOOD & EXHAUST SYSTEM  
CLEANING  
DATE OF CLEANING : 21 & 22 MAY 2019  
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS  
DATE OF NEXT CLEANING : 22 NOVEMBER 2019

*The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines*

*The entire Kitchen Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES