

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



CRYSTALLINE
ENVIRONMENTAL SERVICES




Completion Report for

Kitchen Hood & Exhaust System Cleaning & Degreasing


Date: **15 February 2020**
Client Name: **Emirates Park Zoo & Resort**
Contact Person: **Mr. John Carlo D. Corpuz**
Designation: **Buyer**
Site Detail: **Emirates Park Zoo - Shahama, Abu Dhabi**



Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D. Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Al Dar Kitchen Hood Cleaning 1		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A		Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
Type & Size of Hood Single hood			
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 10 February 2020	Next Cleaning Date 09 May 2020	
Crystalline Representative 		Customer Representative 	

Al Dar Kitchen Hood Cleaning 1

Before Photo



After Photo



Before Photo



After Photo



Kitchen hood Cleaned and Degreased

Al Dar Kitchen Hood Cleaning 1

Before Photo




After Photo



Kitchen hood Cleaned and Degreased

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D. Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Al Dar Kitchen Hood Cleaning 2		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A		Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
Type & Size of Hood Single kitchen hood			
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -		Current Cleaning Date 10 February 2020	
		Next Cleaning Date 09 May 2020	
Crystalline Representative 		Customer Representative 	

Al Dar Kitchen Hood Cleaning 2


Before Photo




After Photo



Before Photo



After Photo



Kitchen hood Cleaned and Degreased

Al Dar Kitchen Hood Cleaning 2

Before Photo



After Photo





Before Photo



After Photo




Kitchen hood Cleaned and Degreased

Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D.Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Al Dar Kitchen Hood Cleaning 3		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A		Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
Type & Size of Hood Single hood			
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 1 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 1 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 11 February 2020	Next Cleaning Date 10 May 2020	
Crystalline Representative 		Customer Representative 	

Al Dar Kitchen Hood Cleaning 3

Before Photo



After Photo



Before Photo



After Photo




Kitchen hood Cleaned and Degreased

Al Dar Kitchen Hood Cleaning 3

Before Photo



After Photo



Before Photo

After Photo



Kitchen hood Cleaned and Degreased

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES PARK ZOO.

CLIENT ADDRESS : P.O. BOX: 111026, ABU DHABI, UAE.

CONTACT PERSON : MR. JOHN CARLO D. CORPUZ

SITE DETAILS : **ALDAR KITCHEN, OLD SHAHAMA, AL BAHYA STREET, ABU DHABI, UAE.**

DETAILS : **KITCHEN HOOD & EXHAUST SYSTEM CLEANING**

DATE OF CLEANING : 10-11 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY THREE (3) MONTHS


DATE OF NEXT CLEANING : 09 MAY 2020

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines

The entire Kitchen Hood & Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES


Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D. Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Hide Kthcthen Hood Cleaning 1		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle <input type="checkbox"/> N/A	Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		Type & Size of Hood Single hood
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 12 February 2020	Next Cleaning Date 11 May 2020	
Crystalline Representative 		Customer Representative 	

Hide Kthcthen Hood Cleaning 1

Before Photo



After Photo



Before Photo



After Photo



Kitchen Hood Cleaned and Degreased

Hide Kthothen Hood Cleaning 1

Before Photo



After Photo



Before Photo



After Photo



Kitchen Hood Cleaned and Degreased

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES PARK ZOO.

CLIENT ADDRESS : P.O. BOX: 111026, ABU DHABI, UAE.

CONTACT PERSON : MR. JOHN CARLO D. CORPUZ

SITE DETAILS : THE HIDE KITCHEN, OLD SHAHAMA,
AL BAHYA STREET, ABU DHABI, UAE.

DETAILS : KITCHEN HOOD & EXHAUST SYSTEM
CLEANING

DATE OF CLEANING : 12 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY THREE (3) MONTHS



DATE OF NEXT CLEANING : 11 MAY 2020

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines

The entire Kitchen Hood & Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D. Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Qsar Al Turath Kitchen Hood Cleaning 1		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A	Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		Type & Size of Hood Single hood
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 13 February 2020	Next Cleaning Date 12 May 2020	
Crystalline Representative 		Customer Representative 	

Yemeni Kitchen Hood Cleaning 1

Before Photo



After Photo



Before Photo



After Photo



Kitchen hood Cleaned and Degreased

Yemeni Kitchen Hood Cleaning 1


Before Photo



After Photo





Before Photo



After Photo



Kitchen hood Cleaned and Degreased


Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D. Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Qsar Al Turath Kitchen Hood Cleaning 2		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A	Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A		Type & Size of Hood Single hood
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A		Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 13 February 2020	Next Cleaning Date 12 May 2020	
Crystalline Representative 		Customer Representative 	

Yemeni Kitchen Hood Cleaning 2

Before Photo



After Photo



Before Photo



After Photo




Kitchen hood Cleaned and Degreased

Yemeni Kitchen Hood Cleaning 2

Before Photo



After Photo





Before Photo



After Photo



Kitchen hood Cleaned and Degreased

Customer: Emirates Park Zoo & Resort		Contact Person: Mr. John Carlo D.Corpuz	
Site: Emirates Park Zoo, Old Shahama, Abu Dhabi		Contact Number: 0555248145	
Description: Qsar Al Turath Kitchen Hood Cleaning 3		Location: Ground Floor	
Type Of Building: <input type="checkbox"/> Commercial <input type="checkbox"/> Hotel <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Restaurant			
Cooking Volume <input type="checkbox"/> High <input type="checkbox"/> Very High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low		Filter Cleaning Frequency <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Type Of Filters <input checked="" type="checkbox"/> Mesh <input type="checkbox"/> Baffle <input type="checkbox"/> N/A		Filters in Place <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	
Type & Size of Hood Single hood			
FIRE PROTECTION SYSTEM			
Kitchen <input checked="" type="checkbox"/> Powder <input type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Others		Cooker Hoods <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Powder <input type="checkbox"/> Others	
Fire Dampers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Fusible Links <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
DUCT WORK			
Duct Made Of <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Others		Physical Entry <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
Access With Tools only <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Partly		Vertical Access <input type="checkbox"/> Rope Access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A	
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:		Condition Of Ducts <input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1		Door / Plates Installed <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No No Doors: 2 No Panels: 1	
Where Installed	Duct Size/Aprox Length Lenght	Location Roof top	Condition Of Roof Good
Insulated <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Damaged <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	Exhaust Fans <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	
Equipments Used <input checked="" type="checkbox"/> Jetting Machine <input checked="" type="checkbox"/> Inlet Water Hose <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Plastics Rool/Bags <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Suitable PPE <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder			
Last Cleaning Date -	Current Cleaning Date 13 February 2020	Next Cleaning Date 12 May 2020	
Crystalline Representative 		Customer Representative 	

Yemeni Kitchen Hood Cleaning 3

Before Photo




After Photo



Before Photo



After Photo



Kitchen hood Cleaned and Degreased

Yemeni Kitchen Hood Cleaning 3

Before Photo



After Photo



Before Photo



After Photo



Kitchen hood Cleaned and Degreased

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES PARK ZOO & RESORT.

CLIENT ADDRESS : P.O. BOX: 111026, ABU DHABI, UAE.

CONTACT PERSON : MR. JOHN CARLO D. CORPUZ

SITE DETAILS : QASR AL TURATH RESTAURANT,
OLD SHAHAMA, ABU DHABI, UAE.

DETAILS : KITCHEN HOOD & EXHAUST SYSTEM
CLEANING

DATE OF CLEANING : 13 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY THREE (3) MONTHS

DATE OF NEXT CLEANING : 12 MAY 2020

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines.

Municipality guidelines

The entire Kitchen Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES