ENVIRONMENTAL SERVICES FOR A GREENER TOMORROW... ONE STEP AT A TIME.

CRYSTALLINE
ENVIRONMENTAL SERVICES

Completion Report for

Water Tank Cleaning & Disinfection

Date: **29 February 2020**
Client Name: **Engineering Office**
Contact Person: **Mr. Narayan MC**
Designation: **MEP Supervisor**
Site Detail: **Zabeel Palace, Dubai-1007**

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17677

CUSTOMER: Eo Facility Management	**CONTACT PERSON:** Mr. Annad
SITE DETAILS: Zabeel Palace Dubai - 1007	**CONTACT NO:** 0503944472
TANK DETAILS: Rcc Water Tank-1	**LOCATION DETAILS:** Upgrade-2

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 8X5X4	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26/02/2020	26/08/2020

CHEMICALS & EQUIPMENTS USED

1. Corela bio and plus _____ Quantity 200 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Rcc Water Tank Cleaning and Disinfected

Crystalline representative: Bishal Rai   **Signature:**

Customer/Customer representative: B. Sindhuja -202177   **Signature:** B. Sindh 202177

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17678

CUSTOMER: EO Facility Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 0503949472
TANK DETAILS: Rcc water Tank-2	LOCATION DETAILS: Upgrade-2

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 8X5X4 USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26/08/2020	26/08/2020

CHEMICALS & EQUIPMENTS USED

1. Cavela bio and plus _____ Quantity 200 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Rcc water Tank Cleaning and Disinfected

Crystalline representative: Bishal Rai	Signature:	
Customer/Customer representative: B.Sindhuja-202177	Signature:	

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17680

CUSTOMER: EO Faciltiy Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zobeel Palace Dubai-1007	CONTACT NO: 0503949472
TANK DETAILS: FRP water Tank	LOCATION DETAILS: Aziza Kitchen

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☑ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 1000 GLN USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26/02/2020	26/08/2020

CHEMICALS & EQUIPMENTS USED

1. Casela bio and plus   Quantity 100 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP water Tank Cleaning and Disinfected

Crystalline representative: Bishal	Signature:
Customer/Customer representative: B. Sindhuja - 202177	Signature: B. Sredhya

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17679

CUSTOMER: Eo Facility Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai -1007	CONTACT NO: 0503949472
TANK DETAILS: Sintex water Tank	LOCATION DETAILS: AsJan Villa

TYPE OF BUILDING: ☐ COMMERCIAL   ☑ RESIDENTIAL   ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☑ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 1000 UGIL USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	26/02/2020	26/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carela bio and plus   Quantity 100 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Sintex water Tank Cleaning and Disinfected

Crystalline representative: Bishal	Signature:
Customer/Customer representative: B. Sindhuja -202177	Signature: 29/02/2020

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17681

CUSTOMER: EO Facility Management	**CONTACT PERSON:** Mr. Anand
SITE DETAILS: Zabeel Palace Dubai-1007	**CONTACT NO:** 0503949472
TANK DETAILS: FRP Water Tank	**LOCATION DETAILS:** Girls Villa Tanks

TYPE OF BUILDING: ☐ COMMERCIAL   ☑ RESIDENTIAL   ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☑ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 4000 GLN USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carela bio and plus   Quantity 150 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP Water Tank Cleaning and Disinfected

Crystalline representative: Bishal   Signature:

Customer/Customer representative: B. Sindhuja - 202177   Signature: B. Sndhj   25/08/202

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17683

CUSTOMER: EO Faciltiy Managemant	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai -1007	CONTACT NO: 0503949472
TANK DETAILS: FRP water Tank-2	LOCATION DETAILS: Dog Kennel

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☑ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK		QUANTITY OF WATER		
M3 1000 Gln USG	L*B*H	☑ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Casela bio and plus   Quantity 100 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP water Tank Cleaning and Disinfected

Crystalline representative: Bshel	Signature:
Customer/Customer representative: B Sindhuja -202177	Signature: B.S... 27/02/2020

...ALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17682

.OMER: EO Faciltiy Managenant	CONTACT PERSON: Mr. Anord
SITE DETAILS: Zabed-Palace Dubai-1007	CONTACT NO: 0503949472
TANK DETAILS: FRP water Tonle-1	LOCATION DETAILS: Dog Kennel

TYPE OF BUILDING: ☐ COMMERCIAL   ✓ RESIDENTIAL   ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	✓ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 1000 GLN USG		L*B*H	☐ FULL	✓ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	✓ DIRTY	☐ VERY DIRTY	✓ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	✓ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ✓ NO	☐ YES ✓ NO	☐ YES ✓ NO	✓ YES ☐ NO	✓ YES ☐ NO	✓ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
✓ YES	☐ NO	✓ YES	☐ NO	✓ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carela bio and plus _____ Quantity 100 ML

2. _____ Quantity _____

✓ Submersibel Pump ✓ High/Low Pressure Jet ✓ Extension Cords ✓ LED Lights ✓ Foot Bath ✓ Ladder

✓ Ventilating Fan ✓ Suction/Discharge Hoses ✓ Oxygen Meter ✓ Vacuum Cleaner ✓ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP water Tank Cleaning and Disinfected

Crystalline representative: Bishel	Signature:
Customer/Customer representative: B Sindhuja - 202177	Signature: B.S... 27/02/202

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17684

CUSTOMER: EO Facitliy Management	CONTACT PERSON: Mr: Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 0503949472
TANK DETAILS: GRP Water Tank	LOCATION DETAILS: ladies Waiting Area

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 2x2x2 USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO ☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carcla bio and plus   Quantity 150 ML

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP Water Tank Cleaning and Disinfected

Crystalline representative: Bishel	Signature:
Customer/Customer representative:	Signature: B Seb 202177

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17685

CUSTOMER: EO Faciltiy Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 050.3949472
TANK DETAILS: GRP Water Tank-1	LOCATION DETAILS: Main gate

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☑ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 1X1X1	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Coodla bio and plus _____ Quantity 100 Ml

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP Water Tank Cleaning and Disinfected

Crystalline representative: Bishel	Signature:
Customer/Customer representative:	Signature: B.

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

17686

WATER TANK - AFTER SERVICE REPORT

CUSTOMER: EO Facility Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 050-3944472
TANK DETAILS: GRP water Tank-2	LOCATION DETAILS: Main gate

TYPE OF BUILDING: ☐ COMMERCIAL   ☑ RESIDENTIAL   ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 1X1X1 USG		L*B*H ☑	FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES ☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Cordla bio and plus _____ Quantity __100 ML__

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☐ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☐ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP water Tank Cleaning and Disinfected

Crystalline representative: Bishal	Signature:
Customer/Customer representative:	Signature: B.Sdh 27/02/22

CLEANER WATER GREENER TOMORROW

CUSTOMER: Eo Facility Management	CONTACT PERSON: Mr: Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 0503949472
TANK DETAILS: GRP water Tank-3	LOCATION DETAILS: Main gate

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 1x1x1 USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Corela bro and plus — Quantity 100 ML

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP water Tank Cleaning and Disinfected

Crystalline representative: Bahd	Signature:
Customer/Customer representative:	Signature: B.Selly 202177

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17688

CUSTOMER: EO Faciltiy Management	CONTACT PERSON: Mr: Anand
SITE DETAILS: Zabeel Palace Dubai-1007	CONTACT NO: 0508949479
TANK DETAILS: GRP Water Tank-4	LOCATION DETAILS: Main gate

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

SIZE OF TANK			QUANTITY OF WATER		
M3 1x1x1 USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / ALFET CLEANING

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Casela bio and plus _____ Quantity 100 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP water Tank Cleaning and Disinfected

Crystalline representative: Bishd	Signature:
Customer/Customer representative:	Signature: B. dolly 7/02/22

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17689

CUSTOMER: EO Facility Management	CONTACT PERSON: Mr. Anand
SITE DETAILS: Zabeel Palace Dubai -1007	CONTACT NO: 050-3949472
TANK DETAILS: FRP Water Tank	LOCATION DETAILS: Police Majlis

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☑ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK / QUANTITY OF WATER

SIZE OF TANK			QUANTITY OF WATER		
M3 3000 GLN USG		L*B*H	☐ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / ALFET CLEANING

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Cazcla bio and plus _____ Quantity 150 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP Water Tank Cleaning and Disinfected

Crystalline representative: Bahel	Signature:
Customer/Customer representative:	Signature: B.Soll 2021/7

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17690

CUSTOMER: Eo Faclty Management	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel Palace floor	CONTACT NO: 050-3009122
TANK DETAILS: GRP Tank 1	LOCATION DETAILS: upgrade 1 outside

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED	☐ POLYURETHANE	☐ OTHERS			

SIZE OF TANK			QUANTITY OF WATER		
M3 22x1 USG		L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	27/02/2020	27/08/2020

CHEMICALS & EQUIPMENTS USED

1. Cidela Lio and pLs _____ Quantity 150 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP water Tank Cleaning and Disinfected

Crystalline representative: BB	Signature:
Customer/Customer representative:	Signature: B.Sely

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17699

CUSTOMER: Ed Faclity mangment	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel pelace Dubai	CONTACT NO: 0503949972
TANK DETAILS: G.R.P. Tank-1	LOCATION DETAILS: West Tank Gate
TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS	

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK / QUANTITY OF WATER

M3	1X1X1	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING / CONDITION OF WATER TANK ALFET CLEANING

☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS / MANHOLE

	ACCESS	MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29.02.2020	29.08.2020

CHEMICALS & EQUIPMENTS USED

1. Corrola Bio pass _____ Quantity 250mi

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Water Tank cleaned and Distrected

Crystalline representative:	Signature: Deepak
Customer/Customer representative:	Signature: B. Selye 20.2.20

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17696

CUSTOMER: EO Facility Management	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel Palace, Dubai 1007	CONTACT NO: 050-3444422
TANK DETAILS: GRP water Tank-2	LOCATION DETAILS: west gate

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☑ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 1X1X1	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES ☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	21/02/2020	21/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carela bio and ph8 _____ Quantity 100 Ml

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder
☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

GRP water Tank cleaning and Disinfected

Crystalline representative: Bishal   Signature:

Customer/Customer representative: Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17698

CUSTOMER: Eo facelity maregment	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel pelace Dubai	CONTACT NO: 050394979
TANK DETAILS: R.C.C water Tank-02	LOCATION DETAILS: Apgoade-01

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☑ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 10x5x4 USG		L*B*H	☐ FULL	☐ HALF	☑ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29.02.2020	29.08.2020

CHEMICALS & EQUIPMENTS USED

1. Caoeca bio pells   Quantity 250 mi

2. _____   Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Water Tanu cleaned and disinfected

Crystalline representative:	Signature:
Customer/Customer representative:	Signature: B. Selly

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17700

CUSTOMER: EO Facility Management	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel Palace - Dubai - 1007	CONTACT NO: 050 3949472
TANK DETAILS: R-CC water Tank-1	LOCATION DETAILS: upgrade-1

TYPE OF BUILDING: ☐ COMMERCIAL ☑ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 10x9x4 USG		☐ L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☑ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
☑ YES ☐ NO	☑ YES ☐ NO	☐ YES ☑ NO	☑ YES ☐ NO	☑ YES ☐ NO	☑ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	29/02/2020	29/08/2020

CHEMICALS & EQUIPMENTS USED

1. Casda bio and plus _____ Quantity 200 ML

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED Lights ☐ Foot Bath ☑ Ladder
☐ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☐ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS AND RECOMMENDATION:

Rcc water Tank Cleaning and Disinfected

Crystalline representative: Bijul	Signature:
Customer/Customer representative:	Signature: B. Del

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17695

CUSTOMER: Eo Facility Management	CONTACT PERSON: Mr Anand
SITE DETAILS: Zabeel Palace Dubai 1007	CONTACT NO: 050 5441472
TANK DETAILS: FRP water Tank-1	LOCATION DETAILS: West gate outside
TYPE OF BUILDING: ☐ COMMERCIAL	✔ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	✔ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3 1500GLN USG		L*B*H	☐ FULL	✔ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK ALFET CLEANING		
☐ CLEAN	✔ DIRTY	☐ VERY DIRTY	✔ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	✔ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS		MANHOLE	☐ COVERED	☐ DAMAGED	☐ NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
✔ YES ☐ NO	✔ YES ☐ NO	☐ YES ✔ NO	✔ YES ☐ NO	✔ YES ☐ NO	✔ YES ☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
✔ YES	☐ NO	✔ YES	☐ NO	✔ YES	☐ NO	☐ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	21/02/2020	21/08/2020

CHEMICALS & EQUIPMENTS USED

1. Carde bio and pbs _____ Quantity 100 ML

2. _____ Quantity _____

☐ Submersibel Pump   ✔ High/Low Pressure Jet   ✔ Extension Cords   ✔ LED Lights   ✔ Foot Bath   ✔ Ladder
✔ Ventilating Fan   ✔ Suction/Discharge Hoses   ✔ Oxygen Meter   ✔ Vacuum Cleaner   ✔ Cleaning Materials

COMMENTS AND RECOMMENDATION:

FRP water Tank cleaning and Disinfected

Crystalline representative:	Signature:
Customer/Customer representative:	Signature:

CLEANER WATER GREENER TOMORROW

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME   : ENGINEERING OFFICE

CONTACT PERSON   : MR. NARAYAN MC

DESIGNATION   : MEP SUPERVISOR

SITE DETAILS   : ZABEEL PALACE, DUBAI-1007

DETAILS   : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING   : FEBRUARY 2020

FREQUENCY OF CLEANING : HALF YEARLY

DATE OF NEXT CLEANING : 26 AUGUST 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.

P.O.Box: 131463

CLEANED & DISINFECTED

Abu Dhabi - U.A.E.

CRYSTAL LINE CLEANING & ENVIRONMENTAL SERVICES

CRYSTALLINE CLEANING AND ENVIRNOMENTAL SERVICES