

WATER TANK CLEANING & DISINFECTION

COMPLETION REPORT

FOR



Client : Cofely Besix Facility Management.

Contact Person: Mr. Paul Pimlott
Facility Manager

Site Details : International Tower, Abu Dhabi,
UAE.

Date : 18 June 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15166

| | | | | | |
|--|---|---|---|---|---|
| CUSTOMER: <i>Cofely Belix FM.</i> | | | CONTACT PERSON: <i>Mr. Sarabjit Singh</i> | | |
| SITE DETAILS: <i>International Tower Abu Dhabi - UAE.</i> | | | CONTACT NO: <i>056 422 1056.</i> | | |
| TANK DETAILS: <i>GRP cold water Tank 1st</i> | | | LOCATION DETAILS: <i>Roof Top.</i> | | |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS | | | | | |
| <u>TYPE OF TANK</u> | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| <u>SIZE OF TANK</u> | | | <u>QUANTITY OF WATER</u> | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| <u>CONDITION OF WATER TANK BEFORE CLEANING</u> | | | <u>CONDITION OF WATER TANK AFTER CLEANING</u> | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| <u>ACCESS</u> | | <u>MANHOLE</u> | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA |
| <u>LADDER IN</u> | <u>LADDER OUT</u> | <u>LEAKS</u> | <u>DRAIN LINE</u> | <u>VALVES</u> | <u>FLOAT VALVE</u> |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <u>TANK CLEANED</u> | | <u>TANK DISINFECTED</u> | | <u>PIPES DISINFECTED</u> | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> NA |
| <u>LAST CLEANING DATE</u> | | <u>CURRENT CLEANING DATE</u> | | <u>NEXT CLEANING DATE</u> | |
| | | <i>10-06-2018</i> | | <i>10-12-2018</i> | |
| <u>CHEMICALS & EQUIPMENTS USED</u> | | | | | |
| 1. <i>Carela Bio Plus</i> Quantity <i>300ml.</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| <u>COMMENTS & RECOMMENDATIONS:</u> <i>Water Tank was cleaned and disinfected.</i> | | | | | |
| Crystalline Representative: <i>Mustaf</i> | | | Signature: <i>[Signature]</i> | | |



CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 10-06-2018

PHOTOGRAPHS
COOLED GRP WATER TANK - PART 01 & 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15167

| | |
|--|---|
| CUSTOMER: <i>Cofely Bestx FM.</i> | CONTACT PERSON: <i>Mr Jasrajit Singh.</i> |
| SITE DETAILS: <i>International Tower Abudhabi - VAC.</i> | CONTACT NO: <i>056 4221056.</i> |
| TANK DETAILS: <i>GRP Water Tank - 1+1</i> | LOCATION DETAILS: <i>Roof Top.</i> |

TYPE OF BUILDING: COMMERCIAL RESIDENTIAL OTHERS

TYPE OF TANK

| | | | | | |
|--|---|-----------------------------------|-------------------------------------|--------------------------------------|----------------------------------|
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | | |

| SIZE OF TANK | QUANTITY OF WATER |
|--------------|-------------------|
|--------------|-------------------|

| | | | | | |
|----|-----|-------|-------------------------------|--|--------------------------------|
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
|----|-----|-------|-------------------------------|--|--------------------------------|

| CONDITION OF WATER TANK BEFORE CLEANING | CONDITION OF WATER TANK AFTER CLEANING |
|---|--|
|---|--|

| | | | | | |
|------------------------------------|--|-------------------------------------|---|-------------------------------------|-------------------------------------|
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |

| ACCESS | MANHOLE | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA |
|--------|---------|---|----------------------------------|-----------------------------|
|--------|---------|---|----------------------------------|-----------------------------|

| | | | | | |
|---|---|---|---|---|---|
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

| | | |
|---|---|---|
| TANK CLEANED | TANK DISINFECTED | PIPES DISINFECTED |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |

| | | |
|---------------------------|------------------------------|---------------------------|
| LAST CLEANING DATE | CURRENT CLEANING DATE | NEXT CLEANING DATE |
| | <i>10-06-2018</i> | <i>10-12-2018</i> |

CHEMICALS & EQUIPMENTS USED

- Carela Bio Eplus* Quantity *300ml.*
- _____ Quantity _____

Submersibel Pump
 High/Low Pressure Jet
 Extension Cords
 LED lights
 Foot Bath
 Ladder
 Ventilating Fan
 Suction/Discharge Hoses
 Oxygen Meter
 Vacuum Cleaner
 Cleaning Materials

COMMENTS & RECOMMENDATIONS: *Water Tank has cleaned and disinfected*

| | |
|---|------------------------|
| Crystalline Representative: <i>Muhammad</i> | Signature: <i>Mu R</i> |
|---|------------------------|



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning, 10-06-2018

PHOTOGRAPHS
UNCOOLED GRP WATER TANK – PART 01 & 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15168

| | | | | | |
|---|--|---|---|---|---|
| CUSTOMER: <i>Copely Betix F.M.</i> | | | CONTACT PERSON: <i>Mr. Sarabjit Singh</i> | | |
| SITE DETAILS: <i>International Tower Abu Dhabi - UAE</i> | | | CONTACT NO: <i>0564221056</i> | | |
| TANK DETAILS: <i>Raw water tank - 01</i> | | | LOCATION DETAILS: <i>Basement</i> | | |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | | <input type="checkbox"/> OTHERS | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input type="checkbox"/> HALF | <input checked="" type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA |
| LADDER IN | | LADDER OUT | | LEAKS | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| DRAIN LINE | | VALVES | | FLOAT VALVE | |
| <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>11-06-2018</i> | | <i>11-12-2018</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Carola Bio plus</i> Quantity <i>500ml.</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder | | | | | |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: <i>Water Tank was cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Mudhip</i> | | | Signature: <i>[Signature]</i> | | |



Date of Cleaning, 11-06-2018

PHOTOGRAPHS
UNDER GROUND RCC RAW WATER TANK - 01

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15169

| | | | | | |
|---|--|---|---|---|---|
| CUSTOMER: <i>Cofely Bedix FM.</i> | | | CONTACT PERSON: <i>Mr. Sarabjit Singh.</i> | | |
| SITE DETAILS: <i>International Tower Abu Dhabi - UAE.</i> | | | CONTACT NO: <i>0564221056.</i> | | |
| TANK DETAILS: <i>RW Raw Tank water - 02</i> | | | LOCATION DETAILS: <i>Basement</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input type="checkbox"/> HALF | <input checked="" type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | | | | | <input type="checkbox"/> NA |
| LADDER IN | | LADDER OUT | | LEAKS | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| DRAIN LINE | | VALVES | | FLOAT VALVE | |
| <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>11-06-2018</i> | | <i>11-12-2018</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Carola Bioplate</i> Quantity <i>500ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: <i>Water Tank Has cleaned and disinfected.</i> | | | | | |
| Crystalline Representative: <i>Mudhaf</i> | | | Signature: <i>[Signature]</i> | | |



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 11-06-2018

PHOTOGRAPHS
UNDER GROUND RCC RAW WATER TANK - 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : COFELY BESIX FACILITY MANAGEMENT.
CLIENT ADDRESS : P.O. BOX: 43139, ABU DHABI, UAE.
CONTACT PERSON : MR. PAUL PIMLOTT.
SITE DETAILS : INTERNATIONAL TOWER, ABU DHABI, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : 10-11 JUNE 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : 10 DECEMBER 2018

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES