

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Water Tank Cleaning & Disinfection

Date: **18 September 2019**
Client Name: **Luxury Facilities Management**
Contact Person: **Mr. Abdelghafour Madi**
Designation: **Manager Facilities**
Site Detail: **Marina Bay & Ocean Scape, Abu Dhabi**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Luxury Facilities Management		Contact Person: Abdelghafour Madi	
Site: Marina Bay & Ocean Scape, Abu Dhabi		Contact Number: +97143731000	
Description: Ocean Scape, Rcc Water Tank 1		Location: Basement 1	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used		Pipes Disinfected	
Chemical: Carela bio		<input type="checkbox"/> Yes	
Chemical: Carela plus		<input checked="" type="checkbox"/> No	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		18 September 2019	
		Next Cleaning Date	
		18 March 2020	
Crystalline Representative		Customer Representative	
			

Ocean Scape, Rcc Water Tank 1

Before Photo



After Photo





Before Photo



After Photo



Mentioned Tank is Cleaned & Disinfected

Customer: Luxury Facilities Management		Contact Person: Abdelghafour Madi	
Site: Marina Bay & Ocean Scape, Abu Dhabi		Contact Number: +97143731000	
Description: Marina Bay, Rcc Water Tank 1		Location: Underground	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
Size of Tank			
M3:	USG:	L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used		Pipes Disinfected	
Chemical: Carela bio		<input type="checkbox"/> Yes	
Quantity: 500ml		<input checked="" type="checkbox"/> No	
Chemical: Carela plus			
Quantity: 500ml			
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		22 September 2019	
		Next Cleaning Date	
		22 March 2020	
Crystalline Representative		Customer Representative	
			

Marina Bay, Rcc Water Tank 1

Before Photo



After Photo



Before Photo



After Photo



Mentioned Tank is Cleaned & Disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : LUXURY FACILITIES MANAGEMENT

CONTACT PERSON : MR. ABDELGHAFOUR MADI

DESIGNATION : MANAGER FACILITIES

SITE DETAILS : MARINA BAY & OCEAN SCAPE, ABU DHABI

DETAILS : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING : SEPTEMBER 2019

FREQUENCY OF CLEANING : HALF YEARLY

DATE OF NEXT CLEANING : 18 MARCH 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Ismanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES